



Light Damage Charges Schedule
1st July 2018

Light Damage Charges Schedule – Cars

Area	Element	Type and Condition	Category									
			Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Front	Badge	Broken/Damaged	51	52	49	97	81	71	63	73	55	80
		Missing	51	52	49	97	81	71	63	73	55	80
	Bonnet	Scratch/Scuff <75mm Paint Damage	249	293	273	308	337	383	395	399	258	284
		Scratch/Scuff - Medium 75-150mm	356	424	395	444	489	533	573	574	355	407
		Scratch/Scuff - Large 150mm+	395	482	449	509	560	619	669	662	416	462
		Dent - Small 25-75mm	288	331	312	347	376	422	433	437	296	323
		Dent - Medium 75-150mm	433	501	472	521	566	610	650	651	432	484
		Dent - Large 150mm+	511	598	565	624	676	735	785	777	532	577
	Bumper Moulding	Broken/Damaged	167	115	106	105	157	49	61	172	163	87
		Missing	167	115	106	105	157	49	61	172	163	87
	Bumper skirt	Broken/Damaged	62	86	70	53	92	64	98	124	138	132
		Missing	62	86	70	53	92	64	98	124	138	132
	Front Bumper	Scratch/Scuff <75mm Paint Damage	252	260	255	239	246	273	246	282	292	273
		Scratch/Scuff - Medium 75-150mm	337	351	345	324	333	366	330	374	386	366
		Scratch/Scuff - Large 150mm+	337	351	345	324	333	366	340	376	386	366
		Dent - Small 25-75mm	291	299	293	277	285	312	285	320	330	311
		Dent - Medium 75-150mm	414	428	422	401	410	443	407	451	463	443
		Dent - Large 150mm+	453	466	461	440	449	482	456	491	501	481
	Front Fog Lamp	Broken/Damaged	69	87	64	97	105		76	147	74	88
		Missing	69	87	64	97	105		76	147	74	88
	Front Grille	Broken/Damaged	167	183	216	162	307	350	392	311	162	234
		Missing	167	183	216	162	307	350	392	311	162	234
	Headlight (Right/Left)	Broken/Damaged	244	240	248	401	289	576	735	836	269	234
		Missing	244	240	248	401	289	576	735	836	269	234
	Indicator (Right/Left)	Broken/Damaged	23	15	35	22	20	26	17	23	10	11
		Missing	23	15	35	22	20	26	17	23	10	11
	Left Front skirt (Right/Left)	Broken/Damaged	62	86	70	53	92	64	98	124	138	132
		Missing	62	86	70	53	92	64	98	124	138	132
	Right Front skirt	Broken/Damaged	62	86	70	53	92	64	98	124	138	132
		Missing	62	86	70	53	92	64	98	124	138	132
	Tow Eye Cover	Broken/Damaged	122	121	117	108	96	73	124	139	110	120
		Missing	122	121	117	108	96	73	124	139	110	120
	Wiper Arm	Broken/Damaged	42	60	63	63	61	64	79	83	43	75
		Missing	42	60	63	63	61	64	79	83	43	75
	Wiper Blades	Broken/Damaged	31	23	33	23	32	35	38	50	25	34
		Missing	31	23	33	23	32	35	38	50	25	34
	Number Plate	Broken/Damaged	25	25	25	25	25	25	25	25	25	25
		Missing	25	25	25	25	25	25	25	25	25	25
	Windscreen	Chipped Glass <5mm	42	42	42	42	42	42	42	42	42	42
Side	Door (Front/Rear)	Scratch/Scuff <75mm Paint Damage	256	246	240	251	257	252	255	272	248	274
		Scratch/Scuff - Medium 75-150mm	488	472	456	490	480	447	488	518	465	529
		Scratch/Scuff - Large 150mm+	654	635	610	666	641	606	662	700	645	716
		Dent - Small 25-75mm	295	285	278	289	296	291	293	311	286	313
		Dent - Medium 75-150mm	565	549	533	567	557	524	565	595	542	606
		Dent - Large 150mm+	770	751	725	782	756	722	778	816	760	832
	Door Handle (Front/Rear)	Broken/Damaged	154	176	163	149	212	155	123	213	155	205
		Scratch/Scuff < 75mm	142	138	136	136	141	145	139	149	129	140
	Door Seal (Front/Rear)	Broken/Damaged	114	50	34	74	71	109	125	111	60	90
	Front Wing	Scratch/Scuff <75mm Paint Damage	179	176	175	186	182	189	194	202	179	195
		Scratch/Scuff - Medium 75-150mm	370	367	358	392	367	349	394	413	368	405
		Scratch/Scuff - Large 150mm+	391	388	378	416	389	373	423	439	396	432
		Dent - Small 25-75mm	218	215	213	224	221	227	233	240	217	233
		Dent - Medium 75-150mm	447	444	435	469	444	426	471	490	445	482
		Dent - Large 150mm+	506	503	493	532	505	489	539	555	511	547
	Fuel Flap	Broken/Damaged	173	165	148	146	146	163	154	154	136	168
		Scratch/Scuff < 75mm	143	140	136	136	142	146	141	151	133	142
	Indicator-Repeater	Broken/Damaged	19	15	13	21				35	11	31
		Missing	19	15	13	21				35	11	31

Light Damage Charges Schedule – Cars

Area	Element	Type and Condition	Category									
			Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Side	Door Mirror Glass	Broken/Damaged	37	51	51	54	76	106	212	180	60	51
		Missing	37	51	51	54	76	106	212	180	60	51
	Mirror Housing	Scratch/Scuff <75mm Paint Damage	75	75	75	75	75	75	75	75	75	75
		Broken/Damaged	119	153	159	236	224	202	307	269	199	162
		Missing	119	153	159	236	224	202	307	269	199	162
	Moulding	Broken/Damaged	221	239	178	295	259	292	485	516	453	285
		Missing	221	239	178	295	259	292	485	516	453	285
	Rear Wing	Scratch/Scuff <75mm Paint Damage	229	213	213	211	224	229	235	240	201	263
		Scratch/Scuff - Medium 75-150mm	443	406	413	432	432	411	459	469	400	511
		Scratch/Scuff - Large 150mm+	482	432	438	464	468	450	501	508	437	561
		Dent - Small 25-75mm	268	252	251	250	263	268	273	278	239	301
		Dent - Medium 75-150mm	520	483	490	509	509	488	536	546	477	588
		Dent - Large 150mm+	597	547	554	580	584	566	617	623	552	676
	Pillar A	Scratch/Scuff <75mm Paint Damage	168	170	163	173	194	166	154	172	161	158
		Scratch/Scuff - Medium 75-150mm	231	237	226	240	273	200	210	234	195	217
		Scratch/Scuff - Large 150mm+	249	256	244	262	302	217	229	251	207	230
		Dent - Small 25-75mm	206	209	202	211	233	205	192	210	200	197
		Dent - Medium 75-150mm	308	314	303	317	350	277	287	311	272	294
		Dent - Large 150mm+	365	372	359	378	418	332	345	367	322	346
	Pillar B	Scratch/Scuff <75mm Paint Damage	178	181	171	186	201	176	181	198	178	213
		Scratch/Scuff - Medium 75-150mm	246	253	240	264	285	216	252	268	244	296
		Scratch/Scuff - Large 150mm+	266	275	259	288	307	235	276	292	275	329
		Dent - Small 25-75mm	216	219	210	224	240	215	220	237	216	251
		Dent - Medium 75-150mm	323	330	317	341	362	293	329	345	321	373
		Dent - Large 150mm+	382	391	375	403	423	351	392	407	391	444
	Pillar D	Scratch/Scuff <75mm Paint Damage								163		169
		Scratch/Scuff - Medium 75-150mm								163		222
		Scratch/Scuff - Large 150mm+								163		237
		Dent - Small 25-75mm								202		208
		Dent - Medium 75-150mm								240		299
		Dent - Large 150mm+								279		352
	Sill	Scratch/Scuff <75mm Paint Damage	180	177	169	177	191	181	181	192	181	177
		Scratch/Scuff - Medium 75-150mm	250	247	236	247	268	252	251	263	247	246
		Scratch/Scuff - Large 150mm+	271	269	256	272	297	276	276	285	279	266
		Dent - Small 25-75mm	219	215	208	216	230	219	220	231	219	216
		Dent - Medium 75-150mm	327	324	313	324	345	329	328	340	324	323
		Dent - Large 150mm+	387	385	371	387	412	391	391	401	394	382
	Underside Protection	Broken/Damaged	115	90	73	61	69	83	99	128	111	84
		Missing	115	90	73	61	69	83	99	128	111	84
	WingTrims	Missing	139	69	19	44	51	75	56	112	100	11
	Wheel Trim (Front/Rear)	Broken/Damaged	66	59	68	78	64			62	55	78
		Missing	66	59	68	78	64			62	55	78
	Wheel Arch (Front/Rear)	Scratch/Scuff <75mm Paint Damage	55	105	68	97	63	52	57	49	52	97
		Scratch/Scuff - Medium 75-150mm	55	105	68	97	63	52	57	49	52	97
		Scratch/Scuff - Large 150mm+	55	105	68	97	63	52	57	49	52	97
		Dent - Small 25-75mm	55	105	68	97	63	52	57	49	52	97
		Dent - Medium 75-150mm	55	105	68	97	63	52	57	49	52	97
		Dent - Large 150mm+	55	105	68	97	63	52	57	49	52	97
	Door Glass	Chipped Glass <5mm	42	42	42	42	42	42	42	42	42	42
	Alloy/Steel Wheel (Front/Rear)	Scratch/Scuff <75mm Paint Damage	65	65	65	65	65	65	65	65	65	65
	Rear Sliding Door	Scratch/Scuff <75mm Paint Damage								495		441
		Scratch/Scuff - Medium 75-150mm								868		784
		Scratch/Scuff - Large 150mm+								1130		1025
		Dent - Small 25-75mm								534		479
		Dent - Medium 75-150mm								945		861
		Dent - Large 150mm+								1246		1141

Light Damage Charges Schedule – Cars

			Category									
Area	Element	Type and Condition	Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Rear	Rear Badge	Broken/Damaged	51	52	49	97	81	71	63	73	55	80
		Missing	51	52	49	97	81	71	63	73	55	80
	Boot lock	Broken/Damaged	50	61	60	76	83	101	115	121	86	141
		Missing	50	61	60	76	83	101	115	121	86	141
	Tailgate/Boot Lid	Scratch/Scuff <75mm Paint Damage	243	258	245	267	279	250	268	275	267	306
		Scratch/Scuff - Medium 75-150mm	345	371	349	380	400	355	372	389	372	442
		Scratch/Scuff - Large 150mm+	385	418	392	427	454	401	442	436	435	506
		Dent - Small 25-75mm	281	297	284	305	317	288	307	314	305	345
		Dent - Medium 75-150mm	422	448	426	457	477	432	449	466	449	519
		Dent - Large 150mm+	501	533	507	543	569	516	557	552	551	622
	Rear Bumper	Scratch/Scuff <75mm Paint Damage	244	258	245	253	245	279	278	285	266	305
		Scratch/Scuff - Medium 75-150mm	330	348	333	341	334	379	372	379	355	408
		Scratch/Scuff - Large 150mm+	330	367	333	341	334	379	377	379	355	408
		Dent - Small 25-75mm	283	297	284	292	283	318	316	324	305	343
		Dent - Medium 75-150mm	407	425	410	418	411	456	449	456	432	485
		Dent - Large 150mm+	446	483	448	456	449	495	493	494	471	524
	Rear Fog Lamp (Right/Left)	Broken/Damaged	127	56	78	31	30			83	123	71
		Missing	127	56	78	31	30			83	123	71
	Rear Light (Right/Left)	Broken/Damaged	99	128	87	127	205	163	205	232	170	148
		Missing	99	128	87	127	205	163	205	232	170	148
	Rear plate light	Broken/Damaged	42	35	29	59	59	29	37	37	22	49
		Missing	42	35	29	59	59	29	37	37	22	49
	Rear Spoiler	Scratch/Scuff <75mm Paint Damage	174	273	186	182	199	175	184	224	200	177
		Scratch/Scuff - Medium 75-150mm	239	379	256	257	274	246	255	308	270	243
		Scratch/Scuff - Large 150mm+	239	379	256	273	274	246	277	308	270	243
		Dent - Small 25-75mm	212	311	224	220	238	214	222	262	238	215
		Dent - Medium 75-150mm	316	456	333	334	351	323	332	385	347	320
		Dent - Large 150mm+	355	494	371	388	389	361	393	424	385	359
	Rear valance	Scratch/Scuff <75mm Paint Damage	174	273	186	182	199	175	184	224	200	177
		Scratch/Scuff - Medium 75-150mm	239	379	256	257	274	246	255	308	270	243
		Scratch/Scuff - Large 150mm+	239	379	256	273	274	246	277	308	270	243
		Dent - Small 25-75mm	212	311	224	220	238	214	222	262	238	215
		Dent - Medium 75-150mm	316	456	333	334	351	323	332	385	347	320
		Dent - Large 150mm+	355	494	371	388	389	361	393	424	385	359
	Tow Eye Cover	Broken/Damaged	111	105	93	22	57	16	15	93	102	122
		Missing	111	105	93	22	57	16	15	93	102	122
	Wiper Arm	Broken/Damaged	40	39	28	33	40	33	39	38	13	42
		Missing	40	39	28	33	40	33	39	38	13	42
	Wiper Blades	Broken/Damaged	31	23	33	23	34	35	38	50	25	35
		Missing	31	23	33	23	34	35	38	50	25	35
	Rear Screen	Glass chip < 5mm	42	42	42	42	42	42	42	42	42	42
	Number Plate	Broken/Damaged	25	25	25	25	25	25	25	25	25	25
		Missing	25	25	25	25	25	25	25	25	25	25
	Rear Loading Door	Scratch/Scuff <75mm Paint Damage										385
		Scratch/Scuff - Medium 75-150mm										561
		Scratch/Scuff - Large 150mm+										656
		Dent - Small 25-75mm										423
		Dent - Medium 75-150mm										638
		Dent - Large 150mm+										772
Roof	Aerial	Broken/Damaged	21	40	21	47	94	340	188	137	24	55
		Missing	21	40	21	47	94	340	188	137	24	55
	Roof	Scratch/Scuff <75mm Paint Damage	256	368	349	366	383	354	381	365	396	455
		Scratch/Scuff - Medium 75-150mm	365	537	508	535	560	489	550	525	550	670
		Scratch/Scuff - Large 150mm+	411	619	583	619	646	565	641	601	672	782
		Dent - Small 25-75mm	294	406	387	405	422	392	420	403	435	494
		Dent - Medium 75-150mm	442	614	585	612	637	566	627	602	627	747
		Dent - Large 150mm+	526	734	699	734	762	681	756	717	788	897

Light Damage Charges Schedule – Cars

Area	Element	Type and Condition	Category									
			Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Roof	Sunroof/ Panoramic Glass Roof	Glass chip < 5mm	42	42	42	42	42	42	42	42	42	42
Interior	Air compressor	Broken/Damaged	43	45	43	92	95	202	202	202	92	95
		Missing	43	45	43	92	95	202	202	202	92	95
	Boot Carpet	Broken/Damaged	113	108	93	130	220	181	223	183	278	333
		Missing	113	108	93	130	220	181	223	183	278	333
	Bulkhead	Broken/Damaged	40	40	40	45	90	130	202	202	45	90
		Missing	40	40	40	45	90	130	202	202	45	90
	Centre Console	Broken/Damaged	81	204	102	227	172	409	463	514	253	95
		Burn/Holed/Cut	81	204	102	227	172	409	463	514	253	95
		Missing	81	204	102	227	172	409	463	514	253	95
	Door Panel	Burn/Holed/Cut	221	239	178	295	259	292	485	516	453	285
		Missing	221	239	178	295	259	292	485	516	453	285
	Front Armrest	Broken/Damaged				90		216	202	202	90	
		Missing				90		216	202	202	90	
	Front Left Seat Back Cover	Broken/Damaged	195	198	228	351	284	352	713	519	258	272
		Burn/Holed/Cut	195	198	228	351	284	352	713	519	258	272
		Missing	195	198	228	351	284	352	713	519	258	272
	Front Left Seat Base Cover	Broken/Damaged	162	168	185	248	292	341	1627	422	278	302
		Burn/Holed/Cut	162	168	185	248	292	341	1627	422	278	302
		Missing	162	168	185	248	292	341	1627	422	278	302
	Front Right Seat Back Cover	Broken/Damaged	195	204	228	382	290	352	713	524	249	262
		Burn/Holed/Cut	195	204	228	382	290	352	713	524	249	262
		Missing	195	204	228	382	290	352	713	524	249	262
	Front Right Seat Base Cover	Broken/Damaged	185	174	194	250	291	325	182	444	285	299
		Burn/Holed/Cut	185	174	194	250	291	325	182	444	285	299
		Missing	185	174	194	250	291	325	182	444	285	299
	Gear Lever Gaiter	Broken/Damaged	42	248	285	386	296	514	400	479	323	686
		Burn/Holed/Cut	42	248	285	386	296	514	400	479	323	686
		Missing	42	248	285	386	296	514	400	479	323	686
	Glove Compartment	Broken/Damaged	132	139	135	172	213	444	170	344	280	163
		Missing	132	139	135	172	213	444	170	344	280	163
	Head Restraint	Broken/Damaged	146	131	116	308	159	160	202	202	308	159
		Missing	146	131	116	308	159	160	202	202	308	159
	Interior Carpet	Burn/Holed/Cut	274	390	409	365	506	554	533	576	353	511
		Missing	274	390	409	365	506	554	533	576	353	511
	Interior Lighting	Broken/Damaged	37	73	39	65	105	311	254	267	45	50
		Missing	37	73	39	65	105	311	254	267	45	50
	Key	Broken/Damaged	326	335	256	314	320	420	374	403	320	253
		Missing	326	335	256	314	320	420	374	403	320	253
	Luggage Cover	Broken/Damaged	109	118	115	119	255	492	395	248	311	263
		Missing	109	118	115	119	255	492	395	248	311	263
	Rear View Mirror	Broken/Damaged	65	96	140	111	199	129	304	239	78	205
		Missing	65	96	140	111	199	129	304	239	78	205
	Rear Armrest	Broken/Damaged				269	92	344	202	202	269	92
		Missing				269	92	344	202	202	269	92
	Rear Left Seat Back Cover	Broken/Damaged	195	194	232	204	252	368	492	597	567	525
		Burn/Holed/Cut	195	194	232	204	252	368	492	597	567	525
		Missing	195	194	232	204	252	368	492	597	567	525
	Rear Left Seat Base Cover	Broken/Damaged	226	268	212	347	374	351	980	539	513	290
		Burn/Holed/Cut	226	268	212	347	374	351	980	539	513	290
		Missing	226	268	212	347	374	351	980	539	513	290
	Rear Right Seat Back Cover	Broken/Damaged	190	197	296	255	267	395	495	582	560	516
		Burn/Holed/Cut	190	197	296	255	267	395	495	582	560	516
		Missing	190	197	296	255	267	395	495	582	560	516
	Rear Right Seat Base Cover	Broken/Damaged	210	251	221	289	415	351	980	532	515	268
		Burn/Holed/Cut	210	251	221	289	415	351	980	532	515	268
		Missing	210	251	221	289	415	351	980	532	515	268

Light Damage Charges Schedule – Cars

			Category									
Area	Element	Type and Condition	Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Interior	Roof lining	Broken/Damaged	153	427	320	427	453	603	662	857	748	841
		Burn/Holed/Cut	153	427	320	427	656	603	628	834	668	995
	SD Card	Broken/Damaged	55	55	55	55	55	400	202	202	55	55
		Missing	55	55	55	55	55	400	202	202	55	55
	Shelves	Broken/Damaged	56	65	61	63	234	427	202	202	63	234
		Missing	56	65	61	63	234	427	202	202	63	234
	Spare Wheel	Broken/Damaged	112	106	65	117	110	207	109	282	82	78
		Missing	112	106	65	117	110	207	109	282	82	78
	Speaker	Broken/Damaged	36	42	42	88	74	43	202	202	88	74
		Missing	36	42	42	88	74	43	202	202	88	74
	Sunvisor	Broken/Damaged	36	106	66	98	92	52	202	202	98	92
		Burn/Holed/Cut	36	106	66	98	92	52	202	202	98	92
		Missing	36	106	66	98	92	52	202	202	98	92
	Switches & Controls	Broken/Damaged	104	196	163	170	467	195	202	202	170	467
		Missing	104	196	163	170	467	195	202	202	170	467
	Window Handle	Broken/Damaged	22	16	16	19	15				11	
		Missing	22	16	16	19	15				11	
	Locking Wheel Bolt Key	Broken/Damaged	30	40	30	52	53	58	202	202	52	53
		Missing	30	40	30	52	53	58	202	202	52	53
	Full Valet Required	Broken/Damaged	85	85	85	85	85	85	85	85	85	85
	Interior Cleaning	Broken/Damaged	35	35	35	35	35	35	35	35	35	35
Accessories	Tool Kit	Missing		24	18	19	29	11	11	22		24
	Hub Covers	Missing	47	28	31	30	26	32	28	28	35	22
		Scratch/Scuff <75mm Paint Damage	30	30	30	30	30	30	30	30	30	30
	Child Seat	Broken/Damaged	40	40	40	40	40	40	40	40	40	40
		Soiled	40	40	40	40	40	40	40	40	40	40

Light Damage Charges Schedule – Vans

			Category					
Area	Element	Type and Condition	CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van – 5 Seats	SWB Crew Van – 6 Seats
Front	Badge	Broken/Damaged	67	80	64	129	66	71
		Missing	67	80	64	129	66	71
	Bonnet	Scratch/Scuff <75mm Paint Damage	269	263	290	328	268	234
		Scratch/Scuff - Medium 75-150mm	388	376	406	474	387	339
		Scratch/Scuff - Large 150mm+	437	426	480	545	436	380
		Dent - Small 25-75mm	307	302	329	366	307	273
		Dent - Medium 75-150mm	465	453	483	551	464	416
		Dent - Large 150mm+	552	542	595	660	551	496
	Bumper Moulding	Broken/Damaged	42	64	90	62	40	92
		Missing	42	64	90	62	40	92
	Bumper skirt	Broken/Damaged	90	95		185	89	67
		Missing	90	95		185	89	67
	Front Bumper	Scratch/Scuff <75mm Paint Damage	211	227	281	281	194	171
		Scratch/Scuff - Medium 75-150mm	291	313	372	376	269	237
		Scratch/Scuff - Large 150mm+	291	313	372	376	269	237
		Dent - Small 25-75mm	249	266	320	319	232	209
		Dent - Medium 75-150mm	368	390	449	453	346	314
		Dent - Large 150mm+	406	429	488	492	385	349
	Front Grille	Broken/Damaged	204	139	222	222	192	159
		Missing	204	139	222	222	192	159
	Headlight (Right/Left)	Broken/Damaged	201	203	235	239	202	183
		Missing	201	203	235	239	202	183
	Indicator (Right/Left)	Broken/Damaged	29	24	12	10	38	15
		Missing	29	24	12	10	38	15

Light Damage Charges Schedule – Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van – 5 Seats	SWB Crew Van – 6 Seats
Front	Front Skirt (Right/Left)	Broken/Damaged	90	95		185	89	67
		Missing	90	95		185	89	67
	Tow Eye Cover	Broken/Damaged	36	37	14		23	11
		Missing	36	37	14		23	11
	Wiper Arm	Broken/Damaged	50	59	54	71	53	72
		Missing	50	59	54	71	53	72
	Wiper Blades	Broken/Damaged	30	26	34	17	31	38
		Missing	30	26	34	17	31	38
	Number Plate	Broken/Damaged	25	25	25	25	25	25
		Missing	25	25	25	25	25	25
	Wind Screen	Glass chip < 5mm	42	42	42	42	42	42
Side (Right/Left)	Door (Front/Rear)	Scratch/Scuff <75mm Paint Damage	262	277	276	253	263	289
		Scratch/Scuff - Medium 75-150mm	507	532	632	501	500	538
		Scratch/Scuff - Large 150mm+	687	723	949	684	672	720
		Dent - Small 25-75mm	300	315	314	292	301	327
		Dent - Medium 75-150mm	584	609	709	578	577	615
		Dent - Large 150mm+	803	838	1065	800	787	836
	Door Handle (Front/Rear)	Broken/Damaged	73	68	75	69	46	68
		Scratch/Scuff <75mm Paint Damage	144	123	125	139	136	139
	Door Seal (Front/Rear)	Broken/Damaged	75	72	37	76	82	63
	Front Wing	Scratch/Scuff <75mm Paint Damage	190	188	196	200	190	189
		Scratch/Scuff - Medium 75-150mm	397	398	520	418	389	388
		Scratch/Scuff - Large 150mm+	422	425	557	448	417	415
		Dent - Small 25-75mm	228	226	235	238	228	227
		Dent - Medium 75-150mm	474	475	597	495	466	465
		Dent - Large 150mm+	538	541	672	564	533	531
	Fuel Flap	Broken/Damaged	146	145	162	198	141	164
		Scratch/Scuff <75mm Paint Damage	138	137	136	144	136	138
	Side Indicator Repeater	Broken/Damaged	23	13		30	26	16
		Missing	23	13		30	26	16
	Door Mirror Glass	Broken/Damaged	42	38	40	52	36	29
		Missing	42	38	40	52	36	29
	Mirror Housing	Scratch/Scuff <75mm Paint Damage	75	75	75	75	75	75
		Broken/Damaged	125	128	169	182	115	140
		Missing	125	128	169	182	115	140
	Moulding (Front/Rear)	Broken/Damaged	135	173	161	41	141	196
		Missing	135	173	161	41	141	196
	Rear Wing	Scratch/Scuff <75mm Paint Damage	269	299	407	289	274	377
		Scratch/Scuff - Medium 75-150mm	522	574	821	555	522	679
		Scratch/Scuff - Large 150mm+	577	636	944	613	581	763
		Dent - Small 25-75mm	308	338	445	327	312	416
		Dent - Medium 75-150mm	599	651	898	632	599	756
		Dent - Large 150mm+	692	752	1060	729	696	878
	Pillar A	Scratch/Scuff <75mm Paint Damage	179	175	152	159	180	
		Scratch/Scuff - Medium 75-150mm	254	248	208	219	257	
		Scratch/Scuff - Large 150mm+	277	271	228	237	281	
		Dent - Small 25-75mm	218	214	191	197	219	
		Dent - Medium 75-150mm	331	325	285	296	334	
		Dent - Large 150mm+	392	387	343	353	396	
	Pillar B	Scratch/Scuff <75mm Paint Damage	176	186	153	182	173	214
		Scratch/Scuff - Medium 75-150mm	246	260	211	253	243	300
		Scratch/Scuff - Large 150mm+	266	286	231	277	262	335
		Dent - Small 25-75mm	214	225	191	220	212	252
		Dent - Medium 75-150mm	323	337	288	330	320	377
		Dent - Large 150mm+	382	401	346	393	378	450

Light Damage Charges Schedule – Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van – 5 Seats	SWB Crew Van – 6 Seats
Side (Right/Left)	Pillar C	Scratch/Scuff <75mm Paint Damage	164	164	162	179	163	
		Scratch/Scuff - Medium 75-150mm	164	164	162	249	163	
		Scratch/Scuff - Large 150mm+	164	164	162	273	163	
		Dent - Small 25-75mm	202	202	201	217	201	
		Dent - Medium 75-150mm	241	241	239	326	240	
		Dent - Large 150mm+	279	279	278	388	278	
	Pillar D	Scratch/Scuff <75mm Paint Damage	194	159	212			164
		Scratch/Scuff - Medium 75-150mm	274	196	298			226
		Scratch/Scuff - Large 150mm+	299	207	337			244
		Dent - Small 25-75mm	233	197	251			202
		Dent - Medium 75-150mm	351	273	375			303
		Dent - Large 150mm+	414	322	452			360
	Sill	Scratch/Scuff <75mm Paint Damage	177	174	151	173	174	179
		Scratch/Scuff - Medium 75-150mm	248	242	204	242	245	250
		Scratch/Scuff - Large 150mm+	271	266	226	261	268	274
		Dent - Small 25-75mm	216	212	189	212	213	217
		Dent - Medium 75-150mm	325	319	281	319	322	327
		Dent - Large 150mm+	387	381	342	376	383	390
	Underside Protection	Broken/Damaged	114	121	87	95	73	73
		Missing	114	121	87	95	73	73
	Wheel Trim (Front/Rear)	Broken/Damaged	63	54	62		135	57
		Missing	63	54	62		135	57
	WingTrims	Missing	58	10	24			10
	Wheel Arch (Front/Rear)	Scratch/Scuff <75mm Paint Damage	142	97	82	214	68	68
		Scratch/Scuff - Medium 75-150mm	142	97	82	214	68	68
		Scratch/Scuff - Large 150mm+	142	97	82	214	68	68
		Dent - Small 25-75mm	142	97	82	214	68	68
		Dent - Medium 75-150mm	142	97	82	214	68	68
		Dent - Large 150mm+	142	97	82	214	68	68
	Door Glass (Front/Rear)	Glass chip < 5mm	42	42	42	42	42	42
	Alloy/Steel Wheel (Front/Rear)	Scratch/Scuff <75mm Paint Damage	65	65	65	65	65	65
	Left Side Rear Panel	Scratch/Scuff <75mm Paint Damage			635			
		Scratch/Scuff - Medium 75-150mm			1153			
		Scratch/Scuff - Large 150mm+			1374			
		Dent - Small 25-75mm			674			
		Dent - Medium 75-150mm			1230			
		Dent - Large 150mm+			1489			
	Right Side Rear Panel	Scratch/Scuff <75mm Paint Damage			635			
		Scratch/Scuff - Medium 75-150mm			1153			
		Scratch/Scuff - Large 150mm+			1374			
		Dent - Small 25-75mm			674			
		Dent - Medium 75-150mm			1230			
		Dent - Large 150mm+			1489			
	Side Wall	Scratch/Scuff <75mm Paint Damage			635			
		Scratch/Scuff - Medium 75-150mm			904			
		Scratch/Scuff - Large 150mm+			1126			
		Dent - Small 25-75mm			674			
		Dent - Medium 75-150mm			981			
		Dent - Large 150mm+			1241			
	Rear Sliding Door	Scratch/Scuff <75mm Paint Damage	307	397	514		304	371
		Scratch/Scuff - Medium 75-150mm	579	717	978		567	669
		Scratch/Scuff - Large 150mm+	775	951	1387		754	877
		Dent - Small 25-75mm	346	435	553		342	409
		Dent - Medium 75-150mm	656	794	1055		644	746
		Dent - Large 150mm+	891	1067	1502		870	992

Light Damage Charges Schedule – Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van – 5 Seats	SWB Crew Van – 6 Seats
Rear	Rear Badge	Broken/Damaged	67	80	64	129	66	71
		Missing	67	80	64	129	66	71
	Boot lock	Broken/Damaged	177	160	143	87	216	124
		Missing	177	160	143	87	216	124
	Tailgate/Boot Lid	Scratch/Scuff <75mm Paint Damage	300	365				
		Scratch/Scuff - Medium 75-150mm	436	524				
		Scratch/Scuff - Large 150mm+	495	615				
		Dent - Small 25-75mm	338	404				
		Dent - Medium 75-150mm	513	601				
		Dent - Large 150mm+	611	731				
	Rear Bumper	Scratch/Scuff <75mm Paint Damage	261	266	234	227		
		Scratch/Scuff - Medium 75-150mm	356	366	353	328		
		Scratch/Scuff - Large 150mm+	356	366	353	367		
		Dent - Small 25-75mm	300	305	273	266		
		Dent - Medium 75-150mm	433	443	430	405		
		Dent - Large 150mm+	471	481	469	482		
	Rear Fog Lamp (Right/Left)	Broken/Damaged	51					
		Missing	51					
	Rear Light (Right/Left)	Broken/Damaged	109	116	94	130	130	144
		Missing	109	116	94	130	130	144
	Rear plate light	Broken/Damaged	31	27	30	33	30	22
		Missing	31	27	30	33	30	22
	Tow Eye Cover	Broken/Damaged	28	14			14	
		Missing	28	14			14	
	Wiper Arm	Broken/Damaged	33	76				
		Missing	33	76				
	Wiper Blades	Broken/Damaged	30	29	34	17	31	38
		Missing	30	29	34	17	31	38
	Rear Screen	Glass chip < 5mm	42	42	42	42	42	42
	Number Plate	Broken/Damaged	25	25	25	25	25	25
		Missing	25	25	25	25	25	25
	Rear Loading Door	Scratch/Scuff <75mm Paint Damage	401	385	567	238	414	454
		Scratch/Scuff - Medium 75-150mm	593	564	810	344	613	666
		Scratch/Scuff - Large 150mm+	687	658	995	386	710	782
		Dent - Small 25-75mm	439	423	606	277	452	492
		Dent - Medium 75-150mm	670	641	887	421	690	743
		Dent - Large 150mm+	803	774	1110	501	825	898
	Step	Broken/Damaged	350	350	350	350	350	350
		Missing	350	350	350	350	350	350
	Tail-lift	Broken/Damaged	450	450	450	450	450	450
		Missing	450	450	450	450	450	450
Roof	Aerial	Broken/Damaged	22	21	55	34	29	23
		Missing	22	21	55	34	29	23
	Roof	Scratch/Scuff <75mm Paint Damage	500	452	366	377	504	702
		Scratch/Scuff - Medium 75-150mm	742	658	520	554	749	1053
		Scratch/Scuff - Large 150mm+	867	775	619	637	876	1246
		Dent - Small 25-75mm	538	491	405	416	543	740
		Dent - Medium 75-150mm	819	735	597	631	826	1130
		Dent - Large 150mm+	982	890	735	752	992	1361
	Sunroof/Panoramic Glass Roof	Glass chip < 5mm	42	42	42	42	42	42
Interior	Air compressor	Broken/Damaged	42	42	42	42	42	42
		Missing	42	42	42	42	42	42
	Bulkhead	Broken/Damaged	402	402	402	402	402	402
		Missing	402	402	402	402	402	402

Light Damage Charges Schedule – Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van – 5 Seats	SWB Crew Van – 6 Seats
Interior	Centre Console	Broken/Damaged	75	71	89	27	66	82
		Burn/Holed/Cut	75	71	89	27	66	82
		Missing	75	71	89	27	66	82
	Door Panel	Burn/Holed/Cut	135	173	161	41	141	196
		Missing	135	173	161	41	141	196
	Front Armrest	Broken/Damaged	160	160	160	160	160	160
		Missing	160	160	160	160	160	160
	Front Left Seat Back Cover	Broken/Damaged	295	341	277	44	163	124
		Burn/Holed/Cut	295	341	277	44	163	124
		Missing	295	341	277	44	163	124
	Front Left Seat Base Cover	Broken/Damaged	206	333	315	51	112	157
		Burn/Holed/Cut	206	333	315	51	112	157
		Missing	206	333	315	51	112	157
	Front Right Seat Back Cover	Broken/Damaged	281	299	244	424	170	111
		Burn/Holed/Cut	281	299	244	424	170	111
		Missing	281	299	244	424	170	111
	Front Right Seat Base Cover	Broken/Damaged	226	366	197	55	105	177
		Burn/Holed/Cut	226	366	197	55	105	177
		Missing	226	366	197	55	105	177
	Gear Lever Gaiter	Broken/Damaged	296	255	270	46	336	305
		Burn/Holed/Cut	296	255	270	46	336	305
		Missing	296	255	270	46	336	305
	Glove Compartment	Broken/Damaged	177	149	215	100	164	86
		Missing	177	149	215	100	164	86
	Head Restraint	Broken/Damaged	151	151	151	151	151	151
		Missing	151	151	151	151	151	151
	Interior Carpet	Burn/Holed/Cut	458	467	295	903	553	233
		Missing	458	467	295	903	553	233
	Interior Lighting	Broken/Damaged	42	38	107	29	33	39
		Missing	42	38	107	29	33	39
	Key	Broken/Damaged	274	267	350	270	270	265
		Missing	274	267	350	270	270	265
	Luggage Cover	Broken/Damaged	199				169	
		Missing	199				169	
	Rear View Mirror	Broken/Damaged	61	39	70	83	28	458
		Missing	61	39	70	83	28	458
	Rear Armrest	Broken/Damaged	179	179	179	179	179	179
		Missing	179	179	179	179	179	179
	Rear Left Seat Back Cover	Broken/Damaged	110			52	152	
		Burn/Holed/Cut	110			52	152	
		Missing	110			52	152	
	Rear Left Seat Base Cover	Broken/Damaged	190	485		135	224	
		Burn/Holed/Cut	190	485		135	224	
		Missing	190	485		135	224	
	Rear Right Seat Back Cover	Broken/Damaged	68	256		52	103	
		Burn/Holed/Cut	68	256		52	103	
		Missing	68	256		52	103	
	Rear Right Seat Base Cover	Broken/Damaged	123	390		135	158	
		Burn/Holed/Cut	123	390		135	158	
		Missing	123	390		135	158	
	Roof lining	Broken/Damaged	272	328	1064	124	543	203
		Burn/Holed/Cut	170	425				
	Spare Wheel	Broken/Damaged	65	74	76	113	100	94
		Missing	65	74	76	113	100	94

Light Damage Charges Schedule – Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van – 5 Seats	SWB Crew Van – 6 Seats
Interior	Speaker	Broken/Damaged	43	43	43	43	43	43
		Missing	43	43	43	43	43	43
	Sunvisor	Broken/Damaged	68	68	68	68	68	68
		Burn/Holed/Cut	68	68	68	68	68	68
		Missing	68	68	68	68	68	68
	Switches & Controls	Broken/Damaged	148	148	148	148	148	148
		Missing	148	148	148	148	148	148
	Window Handle	Broken/Damaged				9		
		Missing				9		
	Locking Wheel Bolt Key	Broken/Damaged	58	58	58	58	58	58
		Missing	58	58	58	58	58	58
	Full Valet Required	Broken/Damaged	85	85	85	85	85	85
	Interior Cleaning	Broken/Damaged	35	35	35	35	35	35
	Ply Lining	Broken/Damaged	60	60	60	60	60	60
		Missing	60	60	60	60	60	60
Accessories	Tool Kit	Missing	41	29	7			
	Hub Covers	Missing	18	22	39	46	17	30
		Scratch/Scuff <75mm Paint Damage	30	30	30	30	30	30
	Child Seat	Broken/Damaged	40	40	40	40	40	40
		Soiled	40	40	40	40	40	40