



**Light Damage Charges Schedule
1st February 2019**

Light Damage Charges Schedule - Cars

Area	Element	Type and Condition	Category									
			Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Front	Badge	Broken/Damaged	51	82	67	80	105	63	64	76	60	68
		Missing	51	82	67	80	105	63	64	76	60	68
	Bonnet	Scratch/Scuff <75mm Paint Damage	231	264	278	305	320	365	389	349	268	265
		Scratch/Scuff - Medium 75-150mm	437	485	508	559	575	586	628	601	507	508
		Scratch/Scuff - Large 150mm+	584	638	665	734	745	705	749	771	675	687
		Dent - Small 25-75mm	231	264	278	305	320	365	389	349	268	265
		Dent - Medium 75-150mm	437	485	508	559	575	586	628	601	507	508
		Dent - Large 150mm+	584	638	665	734	745	705	749	771	675	687
	Bumper Moulding	Broken/Damaged	181	121	181	128	181	185	48	211	259	140
		Missing	181	121	181	128	181	185	48	211	259	140
	Bumper skirt	Broken/Damaged	68	88	99	62	95	58	102	109	103	132
		Missing	68	88	99	62	95	58	102	109	103	132
		Scuffed	68	88	99	62	95	58	102	109	103	132
	Front Bumper	Scratch/Scuff <75mm Paint Damage	234	239	251	226	247	237	224	250	271	250
		Scratch/Scuff - Medium 75-150mm	314	328	344	311	339	321	320	348	366	343
		Scratch/Scuff - Large 150mm+	314	328	344	311	339	321	321	349	366	343
		Dent - Small 25-75mm	234	239	251	226	247	237	224	250	271	250
		Dent - Medium 75-150mm	314	328	344	311	339	321	320	348	366	343
		Dent - Large 150mm+	314	328	344	311	339	321	321	349	366	343
	Fog Light (Right/Left)	Broken/Damaged	54	88	106	94	103		77	155	72	81
		Missing	54	88	106	94	103		77	155	72	81
	Front Grille	Broken/Damaged	164	203	205	204	279	263	189	333	217	251
		Missing	164	203	205	204	279	263	189	333	217	251
	Headlight (Right/Left)	Broken/Damaged	259	242	291	400	381	663	761	839	300	257
		Missing	259	242	291	400	381	663	761	839	300	257
	Indicator (Right/Left)	Broken/Damaged	25	27	14	19	15	26	15	33	27	13
		Missing	25	27	14	19	15	26	15	33	27	13
	Front Skirt (Right/Left)	Broken/Damaged	68	88	99	62	95	58	102	109	103	132
		Missing	68	88	99	62	95	58	102	109	103	132
	Tow Eye Cover	Broken/Damaged	121	124	124	85	125	97	123	118	122	115
		Missing	121	124	124	85	125	97	123	118	122	115
	Wiper Arm	Broken/Damaged	44	67	64	70	58	72	83	74	60	64
Missing		44	67	64	70	58	72	83	74	60	64	
Wiper Blades	Broken/Damaged	33	28	24	24	28	43	38	47	31	39	
	Missing	33	28	24	24	28	43	38	47	31	39	
Number Plate	Broken/Damaged	25	25	25	25	25	25	25	25	25	25	
	Missing	25	25	25	25	25	25	25	25	25	25	
Wind Screen	Glass chip 5-10mm	35	35	35	35	35	35	35	35	35	35	
Side	Door (Front/Rear)	Scratch/Scuff <75mm Paint Damage	238	226	232	242	239	232	241	243	241	260
		Scratch/Scuff - Medium 75-150mm	450	428	437	465	450	400	411	441	467	501
		Scratch/Scuff - Large 150mm+	600	567	580	619	598	510	523	588	628	679
		Dent - Small 25-75mm	238	226	232	242	239	232	241	243	241	260
		Dent - Medium 75-150mm	450	428	437	465	450	400	411	441	467	501
		Dent - Large 150mm+	600	567	580	619	598	510	523	588	628	679
	Door Handle (Front/Rear)	Broken/Damaged	82	103	105	119	154	55	27	104	134	110
		Missing	154	154	152	150	153	110	152	115	154	152
	Door Seal (Front/Rear)	Broken/Damaged	126	31	69	69	57	129	132	117	65	91
	Front Wing	Scratch/Scuff <75mm Paint Damage	160	162	163	174	164	178	185	177	182	172
		Scratch/Scuff - Medium 75-150mm	328	331	335	362	338	318	331	343	379	370
		Scratch/Scuff - Large 150mm+	455	448	455	495	463	422	441	476	522	524
		Dent - Small 25-75mm	160	162	163	174	164	178	185	177	182	172
		Dent - Medium 75-150mm	328	331	335	362	338	318	331	343	379	370
		Dent - Large 150mm+	455	448	455	495	463	422	441	476	522	524
	Fuel Flap	Broken/Damaged	173	151	167	191	147	87	143	136	150	165
		Scratch/Scuff <75mm Paint Damage	123	124	124	127	122	128	93	105	125	117

Light Damage Charges Schedule - Cars

Area	Element	Type and Condition	Category										
			Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium	
Side	Side Indicator Repeater	Broken/Damaged	23	16	17	19	21				26	13	30
		Missing	23	16	17	19	21				26	13	30
	Door Mirror Glass	Broken/Damaged	37	45	51	49	71	217	236	153	59	48	
		Missing	37	45	51	49	71	217	236	153	59	48	
	Mirror Housing	Scratch/Scuff <75mm Paint Damage	106	106	140	145	162	199	130	106	129	135	
		Broken/Damaged	118	166	207	206	199	192	313	272	203	159	
		Missing	118	166	207	206	199	192	313	272	203	159	
	Moulding (Front/Rear)	Broken/Damaged	242	175	298	376	310	520	497	519	563	293	
		Missing	242	175	298	376	310	520	497	519	563	293	
	Rear Wing	Scratch/Scuff <75mm Paint Damage	217	192	205	201	209	225	248	232	208	260	
		Scratch/Scuff - Medium 75-150mm	418	372	380	403	404	382	417	424	416	490	
		Scratch/Scuff - Large 150mm+	563	498	506	543	542	490	528	568	565	663	
		Dent - Small 25-75mm	217	192	205	201	209	225	248	232	208	260	
		Dent - Medium 75-150mm	418	372	380	403	404	382	417	424	416	490	
		Dent - Large 150mm+	563	498	506	543	542	490	528	568	565	663	
	Pillar A	Scratch/Scuff <75mm Paint Damage	148	151	155	159	172	150	137	152	150	158	
		Scratch/Scuff - Medium 75-150mm	315	312	321	336	349	284	314	313	318	344	
		Scratch/Scuff - Large 150mm+	438	428	440	464	479	387	430	436	448	483	
		Dent - Small 25-75mm	148	151	155	159	172	150	137	152	150	158	
		Dent - Medium 75-150mm	315	312	321	336	349	284	314	313	318	344	
		Dent - Large 150mm+	438	428	440	464	479	387	430	436	448	483	
	Pillar B	Scratch/Scuff <75mm Paint Damage	160	159	173	170	180	185	191	209	174	191	
		Scratch/Scuff - Medium 75-150mm	317	325	349	356	362	324	337	361	368	409	
		Scratch/Scuff - Large 150mm+	424	442	474	486	487	427	447	497	519	584	
		Dent - Small 25-75mm	160	159	173	170	180	185	191	209	174	191	
		Dent - Medium 75-150mm	317	325	349	356	362	324	337	361	368	409	
		Dent - Large 150mm+	424	442	474	486	487	427	447	497	519	584	
	Pillar D	Scratch/Scuff <75mm Paint Damage								169		158	
		Scratch/Scuff - Medium 75-150mm								389		337	
		Scratch/Scuff - Large 150mm+								610		512	
		Dent - Small 25-75mm								169		158	
		Dent - Medium 75-150mm								389		337	
		Dent - Large 150mm+								610		512	
	Sill	Scratch/Scuff <75mm Paint Damage	161	170	164	163	179	178	191	188	171	156	
		Scratch/Scuff - Medium 75-150mm	231	245	234	236	255	250	233	275	245	220	
		Scratch/Scuff - Large 150mm+	251	278	255	259	281	254	234	290	269	235	
		Dent - Small 25-75mm	161	170	164	163	179	178	191	188	171	156	
		Dent - Medium 75-150mm	231	245	234	236	255	250	233	275	245	220	
		Dent - Large 150mm+	251	278	255	259	281	254	234	290	269	235	
	Underside Protection	Broken/Damaged	68	113	106	106	75	73	66	68	128	90	
		Missing	68	113	106	106	75	73	66	68	128	90	
	Wheel Trim (Front/Rear)	Broken/Damaged	64	65	77	63	56			62	56	78	
		Missing	64	65	77	63	56			62	56	78	
	WingTrims	Missing	140	38	78	138	58	123	68	171	100	11	
	Wheel Arch (Front/Rear)	Scratch/Scuff <75mm Paint Damage	71	69	75	91	68	59	58	63	62	90	
		Scratch/Scuff - Medium 75-150mm	71	69	76	125	68	59	58	63	62	90	
		Scratch/Scuff - Large 150mm+	71	69	77	158	68	59	58	63	62	90	
		Dent - Small 25-75mm	71	69	75	91	68	59	58	63	62	90	
		Dent - Medium 75-150mm	71	69	76	125	68	59	58	63	62	90	
		Dent - Large 150mm+	71	69	77	158	68	59	58	63	62	90	
	Door Glass (Front/Rear)	Glass chip 5-10mm	35	35	35	35	35	35	35	35	35		
	Alloy/Steel Wheel (Front/Rear)	Scratch/Scuff <75mm Paint Damage	65	65	65	65	65	65	65	65	65		

Light Damage Charges Schedule - Cars

			Category									
Area	Element	Type and Condition	Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Side	Rear Sliding Door	Scratch/Scuff <75mm Paint Damage								622		441
		Scratch/Scuff - Medium 75-150mm								1064		768
		Scratch/Scuff - Large 150mm+								1285		996
		Dent - Small 25-75mm								622		441
		Dent - Medium 75-150mm								1064		768
		Dent - Large 150mm+								1285		996
Rear	Rear Badge	Broken/Damaged	51	82	67	80	105	63	64	76	60	68
		Missing	51	82	67	80	105	63	64	76	60	68
	Boot lock	Broken/Damaged	68	61	81	82	87	86	112	118	73	47
		Missing	68	61	81	82	87	86	112	118	73	47
	Tailgate/Boot Lid	Scratch/Scuff <75mm Paint Damage	226	233	242	252	256	223	276	257	266	302
		Scratch/Scuff - Medium 75-150mm	428	433	454	472	475	427	529	452	497	560
		Scratch/Scuff - Large 150mm+	575	572	601	618	627	569	691	618	652	748
		Dent - Small 25-75mm	226	233	242	252	256	223	276	257	266	302
		Dent - Medium 75-150mm	428	433	454	472	475	427	529	452	497	560
		Dent - Large 150mm+	575	572	601	618	627	569	691	618	652	748
	Rear Bumper	Scratch/Scuff <75mm Paint Damage	228	239	250	203	247	251	248	236	251	268
		Scratch/Scuff - Medium 75-150mm	310	327	342	283	339	354	354	333	341	369
		Scratch/Scuff - Large 150mm+	310	327	359	283	339	356	354	333	341	369
		Dent - Small 25-75mm	228	239	250	203	247	251	248	236	251	268
		Dent - Medium 75-150mm	310	327	342	283	339	354	354	333	341	369
		Dent - Large 150mm+	310	327	359	283	339	356	354	333	341	369
	Rear Fog Lamp (Right/Left)	Broken/Damaged	140	48	65	47	33		121	106	74	77
		Missing	140	48	65	47	33		121	106	74	77
	Rear Light (Right/Left)	Broken/Damaged	100	91	129	183	170	199	203	211	224	147
		Missing	100	91	129	183	170	199	203	211	224	147
	Rear plate light	Broken/Damaged	38	40	43	59	43	35	37	36	28	51
		Missing	38	40	43	59	43	35	37	36	28	51
	Rear Spoiler	Scratch/Scuff <75mm Paint Damage	154	170	224	169	180	167	213	171	192	159
		Scratch/Scuff - Medium 75-150mm	220	242	314	242	258	239	289	244	263	225
		Scratch/Scuff - Large 150mm+	220	242	314	252	258	240	289	251	263	225
		Dent - Small 25-75mm	154	170	224	169	180	167	213	171	192	159
		Dent - Medium 75-150mm	220	242	314	242	258	239	289	244	263	225
		Dent - Large 150mm+	220	242	314	252	258	240	289	251	263	225
	Rear valance	Scratch/Scuff <75mm Paint Damage	154	170	224	169	180	167	213	171	192	159
		Scratch/Scuff - Medium 75-150mm	220	242	314	242	258	239	289	244	263	225
		Scratch/Scuff - Large 150mm+	220	242	314	252	258	240	289	251	263	225
		Dent - Small 25-75mm	154	170	224	169	180	167	213	171	192	159
		Dent - Medium 75-150mm	220	242	314	242	258	239	289	244	263	225
		Dent - Large 150mm+	220	242	314	252	258	240	289	251	263	225
	Tow Eye Cover	Broken/Damaged	117	76	85	21	85	46	105	88	94	121
		Missing	117	76	85	21	85	46	105	88	94	121
	Wiper Arm	Broken/Damaged	41	32	41	41	47	71	83	58	38	38
		Missing	41	32	41	41	47	71	83	58	38	38
	Wiper Blades	Broken/Damaged	33	28	24	24	28	43	38	47	31	39
		Missing	33	28	24	24	28	43	38	47	31	39
	Rear Screen	Glass chip 5-10mm	35	35	35	35	35	35	35	35	35	35
	Number Plate	Broken/Damaged	25	25	25	25	25	25	25	25	25	25
		Missing	25	25	25	25	25	25	25	25	25	25
	Rear Loading Door	Scratch/Scuff <75mm Paint Damage										375
		Scratch/Scuff - Medium 75-150mm										556
		Scratch/Scuff - Large 150mm+										654
		Dent - Small 25-75mm										375
		Dent - Medium 75-150mm										556
		Dent - Large 150mm+										654

Light Damage Charges Schedule - Cars

Area	Element	Type and Condition	Category									
			Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Roof	Aerial	Broken/Damaged	15	20	71	104	112	193	179	88	22	62
		Missing	15	20	71	104	112	193	179	88	22	62
	Roof	Scratch/Scuff <75mm Paint Damage	223	340	362	366	332	354	363	346	344	491
		Scratch/Scuff - Medium 75-150mm	324	500	533	546	488	477	485	482	509	712
		Scratch/Scuff - Large 150mm+	365	575	613	633	562	500	495	540	589	816
		Dent - Small 25-75mm	223	340	362	366	332	354	363	346	344	491
		Dent - Medium 75-150mm	324	500	533	546	488	477	485	482	509	712
		Dent - Large 150mm+	365	575	613	633	562	500	495	540	589	816
	Sunroof/ Panoramic Glass Roof	Glass chip 5-10mm	35	35	35	35	35	35	35	35	35	35
	Interior	Air compressor	Broken/Damaged	43	45	43	92	95	202	202	202	92
Missing			43	45	43	92	95	202	202	202	92	95
Boot Carpet		Broken/Damaged	113	102	179	152	261	137	207	207	437	380
		Missing	113	102	179	152	261	137	207	207	437	380
Bulkhead		Broken/Damaged	40	40	40	45	90	130	202	202	45	90
		Missing	40	40	40	45	90	130	202	202	45	90
Centre Console		Broken/Damaged	81	114	181	224	177	438	516	463	234	86
		Burn/Holed/Cut	81	114	181	224	177	438	516	463	234	86
		Missing	81	114	181	224	177	438	516	463	234	86
Door Panel		Burn/Holed/Cut	242	175	287	376	310	520	497	519	563	293
		Missing	242	175	298	376	310	520	497	519	563	293
Front Armrest		Broken/Damaged				90		216	202	202	90	
		Missing				90		216	202	202	90	
Front Left Seat Back Cover		Broken/Damaged	262	232	268	355	288	306	562	397	422	350
		Burn/Holed/Cut	262	232	268	355	288	306	562	397	422	350
		Missing	262	232	268	355	288	306	562	397	422	350
Front Left Seat Base Cover		Broken/Damaged	166	180	198	236	262	314	1100	422	373	294
		Burn/Holed/Cut	166	180	198	236	262	314	1100	422	373	294
		Missing	166	180	198	236	262	314	1100	422	373	294
Front Right Seat Back Cover		Broken/Damaged	262	230	274	328	287	306	562	403	424	339
		Burn/Holed/Cut	262	230	274	328	287	306	562	403	424	339
		Missing	262	230	274	328	287	306	562	403	424	339
Front Right Seat Base Cover		Broken/Damaged	186	181	197	250	252	674	1100	482	381	300
		Burn/Holed/Cut	186	181	197	250	252	674	1100	482	381	300
		Missing	186	181	197	250	252	674	1100	482	381	300
Gear Lever Gaiter		Broken/Damaged	244	70	61	54	54	83	86	141	72	37
		Burn/Holed/Cut	244	70	61	54	54	83	86	141	72	37
		Missing	244	70	61	54	54	83	86	141	72	37
Glove Compartment		Broken/Damaged	139	160	160	166	231	492	187	318	243	140
		Missing	139	160	160	166	231	492	187	318	243	140
Head Restraint		Broken/Damaged	146	131	116	308	159	160	202	202	308	159
		Missing	146	131	116	308	159	160	202	202	308	159
Interior Carpet		Burn/Holed/Cut	446	585	490	528	517	473	520	617	563	587
		Missing	446	585	490	528	517	473	520	617	563	587
Interior Lighting		Broken/Damaged	36	54	112	87	91	308	270	316	85	97
		Missing	36	54	112	87	91	308	270	316	85	97
Key		Broken/Damaged	185	106	126	265	182	260	341	403	320	131
		Missing	185	106	126	265	182	260	341	403	320	131
Luggage Cover		Broken/Damaged	98	113	188	171	248	325	409	301	260	265
		Missing	98	113	188	171	248	325	409	301	260	265
Rear View Mirror	Broken/Damaged	84	84	111	90	226	291	324	275	143	203	
	Missing	84	84	111	90	226	291	324	275	143	203	
Rear Armrest	Broken/Damaged				269	92	344	202	202	269	92	
	Missing				269	92	344	202	202	269	92	

Light Damage Charges Schedule - Cars

Area	Element	Type and Condition	Category									
			Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Interior	Rear Left Seat Back Cover	Broken/Damaged	185	176	218	209	299	223	239	603	489	322
		Burn/Holed/Cut	185	176	218	209	299	223	239	603	489	322
		Missing	185	176	218	209	299	223	239	603	489	322
	Rear Left Seat Base Cover	Broken/Damaged	232	168	255	342	210	351	351	426	418	351
		Burn/Holed/Cut	232	168	255	342	210	351	351	426	418	351
		Missing	232	168	255	342	210	351	351	426	418	351
	Rear Right Seat Back Cover	Broken/Damaged	180	188	234	232	310	214	247	514	499	312
		Burn/Holed/Cut	180	188	234	232	310	214	247	514	499	312
		Missing	180	188	234	232	310	214	247	514	499	312
	Rear Right Seat Base Cover	Broken/Damaged	181	99	210	239	199	351	351	501	420	326
		Burn/Holed/Cut	181	99	210	239	198	351	351	501	420	326
		Missing	181	99	210	239	199	351	351	501	420	326
	Roof lining	Broken/Damaged	182	389	581	484	598	801	657	726	843	756
		Burn/Holed/Cut	182	389	581	484	598	801	657	726	843	756
	SD Card	Broken/Damaged	55	55	55	55	55	400	202	202	55	55
		Missing	55	55	55	55	55	400	202	202	55	55
	Shelves	Broken/Damaged	56	65	61	63	234	427	202	202	63	234
		Missing	56	65	61	63	234	427	202	202	63	234
	Spare Wheel	Broken/Damaged	109	62	113	119	235	147	106	269	94	84
		Missing	109	62	113	119	235	147	106	269	94	84
	Speaker	Broken/Damaged	36	42	42	88	74	43	202	202	88	74
		Missing	36	42	42	88	74	43	202	202	88	74
	Sunvisor	Broken/Damaged	36	106	66	98	92	52	202	202	98	92
		Burn/Holed/Cut	36	106	66	98	92	52	202	202	98	92
		Missing	36	106	66	98	92	52	202	202	98	92
	Switches & Controls	Broken/Damaged	104	196	163	170	467	195	202	202	170	467
		Missing	104	196	163	170	467	195	202	202	170	467
	Window Handle	Broken/Damaged	23	21	17	20	12				11	
		Missing	23	21	17	20	12				11	
	Locking Wheel Bolt Key	Broken/Damaged	30	40	30	52	53	58	202	202	52	53
Missing		30	40	30	52	53	58	202	202	52	53	
Full Valet Required	Broken/Damaged	60	60	60	60	60	60	60	60	60	60	
	Soiled	60	60	60	60	60	60	60	60	60	60	
Interior Cleaning	Broken/Damaged	35	35	35	35	35	35	35	35	35	35	
Accessories	Tool Kit	Missing		19	24	52	12	11	11	23		29
	Hub Covers	Missing	48	24	31	29	30	29	28	32	33	20
		Scratch/Scuff <75mm Paint Damage	30	30	30	30	30	30	30	30	30	30
	Child Seat	Broken/Damaged	40	40	40	40	40	40	40	40	40	40
		Soiled	40	40	40	40	40	40	40	40	40	40

Light Damage Charges Schedule - Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van - 5 Seats	SWB Crew Van - 6 Seats
Front	Badge	Broken/Damaged	63	76	43	141	71	71
		Missing	63	76	43	141	71	71
	Bonnet	Scratch/Scuff <75mm Paint Damage	255	227	262	354	256	221
		Scratch/Scuff - Medium 75-150mm	515	536	552	661	515	495
		Scratch/Scuff - Large 150mm+	705	781	768	879	703	705
		Dent - Small 25-75mm	255	227	262	354	256	221
		Dent - Medium 75-150mm	515	536	552	661	515	495
		Dent - Large 150mm+	705	781	768	879	703	705
	Bumper Moulding	Broken/Damaged	51	94	77	57	41	101
		Missing	51	94	77	57	41	101
	Bumper skirt	Broken/Damaged	84	77	92	204	95	71
		Missing	84	77	92	204	95	71
		Scuffed	84	77	92	204	95	71
	Front Bumper	Scratch/Scuff <75mm Paint Damage	216	199	250	284	181	158
		Scratch/Scuff - Medium 75-150mm	299	278	312	384	257	225
		Scratch/Scuff - Large 150mm+	302	403	312	384	257	225
		Dent - Small 25-75mm	216	199	250	284	181	158
		Dent - Medium 75-150mm	299	278	312	384	257	225
		Dent - Large 150mm+	302	403	312	384	257	225
	Front Grille	Broken/Damaged	211	163	152	278	202	163
		Missing	211	163	152	278	202	163
	Headlight (Right/Left)	Broken/Damaged	213	275	206	251	214	277
		Missing	213	275	206	251	214	277
	Indicator (Right/Left)	Broken/Damaged	28	14	14	10	40	15
		Missing	28	14	14	10	40	15
	Front Skirt (Right/Left)	Broken/Damaged	84	77	92	204	95	71
		Missing	84	77	92	204	95	71
	Tow Eye Cover	Broken/Damaged	21	29	12	16	24	12
		Missing	21	29	12	16	24	12
	Wiper Arm	Broken/Damaged	53	71	53	141	57	77
		Missing	53	71	53	138	57	77
	Wiper Blades	Broken/Damaged	31	37	34	17	32	39
Missing		31	37	34	17	32	39	
Number Plate	Broken/Damaged	25	25	25	25	25	25	
	Missing	25	25	25	25	25	25	
Wind Screen	Glass chip 5-10mm	35	35	35	35	35	35	
Side	Door (Front/Rear)	Scratch/Scuff <75mm Paint Damage	251	279	283	240	250	276
		Scratch/Scuff - Medium 75-150mm	506	608	579	487	503	570
		Scratch/Scuff - Large 150mm+	695	868	798	671	691	797
		Dent - Small 25-75mm	251	279	283	240	250	276
		Dent - Medium 75-150mm	506	608	579	487	503	570
		Dent - Large 150mm+	695	868	798	671	691	797
	Door Handle (Front/Rear)	Broken/Damaged	33	44	35	36	24	35
		Scratch/Scuff <75mm Paint Damage	210	121	154	154	154	154
	Door Seal (Front/Rear)	Broken/Damaged	70	63	30	76	88	59
	Front Wing	Scratch/Scuff <75mm Paint Damage	174	175	175	181	177	177
		Scratch/Scuff - Medium 75-150mm	390	452	426	398	392	421
		Scratch/Scuff - Large 150mm+	558	683	630	560	560	619
		Dent - Small 25-75mm	174	175	175	181	177	177
		Dent - Medium 75-150mm	390	452	426	398	392	421
		Dent - Large 150mm+	558	683	630	560	560	619

Light Damage Charges Schedule - Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van - 5 Seats	SWB Crew Van - 6 Seats
Side	Fuel Flap	Broken/Damaged	152	164	155	204	142	169
		Scratch/Scuff <75mm Paint Damage	124	124	117	128	123	125
	Side Indicator Repeater	Broken/Damaged	22	16		31	27	16
		Missing	22	16		31	27	16
	Door Mirror Glass	Broken/Damaged	41	32	43	54	38	27
		Missing	41	32	43	54	38	27
	Mirror Housing	Scratch/Scuff <75mm Paint Damage	128	135	107	106	129	106
		Broken/Damaged	132	148	138	192	121	147
		Missing	132	148	138	192	121	147
	Moulding (Front/Rear)	Broken/Damaged	172	221	170	291	151	217
		Missing	172	221	170	291	151	217
	Rear Wing	Scratch/Scuff <75mm Paint Damage	270	368	443	302	261	362
		Scratch/Scuff - Medium 75-150mm	541	761	822	581	525	708
		Scratch/Scuff - Large 150mm+	745	1028	1070	782	724	960
		Dent - Small 25-75mm	270	368	443	302	261	362
		Dent - Medium 75-150mm	541	761	822	581	525	708
		Dent - Large 150mm+	745	1028	1070	782	724	960
	Pillar A	Scratch/Scuff <75mm Paint Damage	159	190	144	141	168	
		Scratch/Scuff - Medium 75-150mm	364	452	364	338	385	
		Scratch/Scuff - Large 150mm+	520	667	558	492	549	
		Dent - Small 25-75mm	159	190	144	141	168	
		Dent - Medium 75-150mm	364	452	364	338	385	
		Dent - Large 150mm+	520	667	558	492	549	
	Pillar B	Scratch/Scuff <75mm Paint Damage	167	199	171	214	161	201
		Scratch/Scuff - Medium 75-150mm	380	491	410	455	371	457
		Scratch/Scuff - Large 150mm+	543	733	614	630	530	661
Dent - Small 25-75mm		167	199	171	214	161	201	
Dent - Medium 75-150mm		380	491	410	455	371	457	
Dent - Large 150mm+		543	733	614	630	530	661	
Pillar C	Scratch/Scuff <75mm Paint Damage	151	164	144	175	150		
	Scratch/Scuff - Medium 75-150mm	292	164	320	384	290		
	Scratch/Scuff - Large 150mm+	433	164	495	545	430		
	Dent - Small 25-75mm	151	202	144	175	150		
	Dent - Medium 75-150mm	292	241	320	384	290		
	Dent - Large 150mm+	433	279	495	545	430		
Pillar D	Scratch/Scuff <75mm Paint Damage	181	148	188	201		151	
	Scratch/Scuff - Medium 75-150mm	431	354	478	515		393	
	Scratch/Scuff - Large 150mm+	633	539	719	778		591	
	Dent - Small 25-75mm	181	148	188	201		151	
	Dent - Medium 75-150mm	431	354	478	515		393	
	Dent - Large 150mm+	633	539	719	778		591	
Sill	Scratch/Scuff <75mm Paint Damage	166	161	141	158	162	166	
	Scratch/Scuff - Medium 75-150mm	238	225	201	227	232	238	
	Scratch/Scuff - Large 150mm+	262	242	218	246	255	262	
	Dent - Small 25-75mm	166	161	141	158	162	166	
	Dent - Medium 75-150mm	238	225	201	227	232	238	
	Dent - Large 150mm+	262	242	218	246	255	262	
Underside Protection	Broken/Damaged	88	78	57	140	71	71	
	Missing	88	78	57	140	71	71	
Wheel Trim (Front/Rear)	Broken/Damaged	44	54	46	46		54	
	Missing	44	54	46	46		54	
WingTrims	Missing	50	10	33	65		10	

Light Damage Charges Schedule - Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van - 5 Seats	SWB Crew Van - 6 Seats
Side	Wheel Arch (Front/Rear)	Scratch/Scuff <75mm Paint Damage	78	70	67	96	76	75
		Scratch/Scuff - Medium 75-150mm	78	70	67	96	76	75
		Scratch/Scuff - Large 150mm+	78	70	67	96	76	75
		Dent - Small 25-75mm	78	70	67	96	76	75
		Dent - Medium 75-150mm	78	70	67	96	76	75
		Dent - Large 150mm+	78	70	67	96	76	75
	Door Glass (Front/Rear)	Glass chip 5-10mm	35	35	35	35	35	35
	Alloy/Steel Wheel (Front/Rear)	Scratch/Scuff <75mm Paint Damage	65	65	65	65	65	65
	Left Side Rear Panel	Scratch/Scuff <75mm Paint Damage			265	191		
		Scratch/Scuff - Medium 75-150mm			526	419		
		Scratch/Scuff - Large 150mm+			787	647		
		Dent - Small 25-75mm			265	191		
		Dent - Medium 75-150mm			526	419		
		Dent - Large 150mm+			787	647		
	Right Side Rear Panel	Scratch/Scuff <75mm Paint Damage			265	191		
		Scratch/Scuff - Medium 75-150mm			526	419		
		Scratch/Scuff - Large 150mm+			787	647		
		Dent - Small 25-75mm			265	191		
		Dent - Medium 75-150mm			526	419		
		Dent - Large 150mm+			787	647		
	Side Wall	Scratch/Scuff <75mm Paint Damage			265	191		
		Scratch/Scuff - Medium 75-150mm			526	419		
		Scratch/Scuff - Large 150mm+			787	647		
		Dent - Small 25-75mm			265	191		
Dent - Medium 75-150mm				526	419			
Dent - Large 150mm+				787	647			
Rear Sliding Door	Scratch/Scuff <75mm Paint Damage	289	407	506	489	291	501	
	Scratch/Scuff - Medium 75-150mm	571	804	912	962	570	917	
	Scratch/Scuff - Large 150mm+	778	1098	1162	1316	773	1223	
	Dent - Small 25-75mm	289	407	506	489	291	501	
	Dent - Medium 75-150mm	571	804	912	962	570	917	
	Dent - Large 150mm+	778	1098	1162	1316	773	1223	
Rear	Rear Badge	Broken/Damaged	63	76	43	141	71	71
		Missing	63	76	43	141	71	71
	Boot lock	Broken/Damaged	199	132	140	86	235	130
		Missing	199	132	140	86	235	130
	Tailgate/Boot Lid	Scratch/Scuff <75mm Paint Damage	265	476				
		Scratch/Scuff - Medium 75-150mm	544	865				
		Scratch/Scuff - Large 150mm+	752	1122				
		Dent - Small 25-75mm	265	476				
		Dent - Medium 75-150mm	544	865				
		Dent - Large 150mm+	752	1122				

Light Damage Charges Schedule - Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van - 5 Seats	SWB Crew Van - 6 Seats
Rear	Rear Bumper	Scratch/Scuff <75mm Paint Damage	212	272	184	193		304
		Scratch/Scuff - Medium 75-150mm	293	393	215	279		451
		Scratch/Scuff - Large 150mm+	293	393	215	315		451
		Dent - Small 25-75mm	212	272	184	193		304
		Dent - Medium 75-150mm	293	393	215	279		451
		Dent - Large 150mm+	293	393	215	315		451
	Rear Fog Lamp (Right/Left)	Broken/Damaged	52	73				
		Missing	52	73				
	Rear Light (Right/Left)	Broken/Damaged	114	134	101	126	131	147
		Missing	114	134	101	126	131	147
	Rear plate light	Broken/Damaged	36	25	30	35	32	23
		Missing	36	25	30	35	32	23
	Tow Eye Cover	Broken/Damaged	14	16			15	
		Missing	14	16			15	
	Wiper Arm	Broken/Damaged	49	71	53	73	57	77
		Missing	49	71	53	73	57	77
	Wiper Blades	Broken/Damaged	31	37	34	17	32	39
		Missing	31	37	34	17	32	39
	Rear Screen	Glass chip 5-10mm	35	35	35	35	35	35
	Number Plate	Broken/Damaged	25	25	25	25	25	25
		Missing	25	25	25	25	25	25
	Rear Loading Door	Scratch/Scuff <75mm Paint Damage	383	425	557	239	401	441
		Scratch/Scuff - Medium 75-150mm	572	626	813	351	601	653
		Scratch/Scuff - Large 150mm+	665	734	896	398	697	768
		Dent - Small 25-75mm	383	425	557	239	401	441
		Dent - Medium 75-150mm	572	626	813	351	601	653
		Dent - Large 150mm+	665	734	896	398	697	768
	Step	Broken/Damaged	350	350	350	350	350	350
		Missing	350	350	350	350	350	350
	Tail-lift	Broken/Damaged	450	450	450	450	450	450
Missing		450	450	450	450	450	450	
Roof	Aerial	Broken/Damaged	28	23	112	36	30	26
		Missing	28	23	112	36	30	26
	Roof	Scratch/Scuff <75mm Paint Damage	484	633	334	356	491	725
		Scratch/Scuff - Medium 75-150mm	723	947	469	527	737	1095
		Scratch/Scuff - Large 150mm+	845	1112	512	609	863	1299
		Dent - Small 25-75mm	484	633	334	356	491	725
		Dent - Medium 75-150mm	723	947	469	527	737	1095
		Dent - Large 150mm+	845	1112	512	609	863	1299
	Sunroof/ Panoramic Glass Roof	Glass chip 5-10mm	35	35	35	35	35	35
	Interior	Air compressor	Broken/Damaged	42	42	42	42	42
Missing			42	42	42	42	42	42
Bulkhead		Broken/Damaged	402	402	402	402	402	402
		Missing	402	402	402	402	402	402
Centre Console		Broken/Damaged	85	83	91	32	69	85
		Burn/Holed/Cut	85	83	91	32	69	85
		Missing	85	83	91	32	69	85
Door Panel		Burn/Holed/Cut	171	221	170	53	151	217
		Missing	171	221	170	53	151	217
Front Armrest		Broken/Damaged	160	160	160	160	160	160
		Missing	160	160	160	160	160	160

Light Damage Charges Schedule – Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van - 5 Seats	SWB Crew Van - 6 Seats
Interior	Front Left Seat Back Cover	Broken/Damaged	218	187	229	472	177	127
		Burn/Holed/Cut	218	187	229	472	177	127
		Missing	218	187	229	472	177	127
	Front Left Seat Base Cover	Broken/Damaged	191	170	285	200	120	95
		Burn/Holed/Cut	191	170	285	200	120	95
		Missing	191	170	285	200	120	95
	Front Right Seat Back Cover	Broken/Damaged	206	119	170	473	185	104
		Burn/Holed/Cut	206	119	170	473	185	104
		Missing	206	119	170	473	185	104
	Front Right Seat Base Cover	Broken/Damaged	241	185	146	305	112	105
		Burn/Holed/Cut	241	185	146	305	112	105
		Missing	241	185	146	305	112	105
	Gear Lever Gaiter	Broken/Damaged	118	238	251	74	169	48
		Burn/Holed/Cut	118	238	251	74	169	48
		Missing	118	238	251	74	169	48
	Glove Compartment	Broken/Damaged	159	93	196	124	178	84
		Missing	159	93	196	124	178	84
	Head Restraint	Broken/Damaged	151	151	151	151	151	151
		Missing	151	151	151	151	151	151
	Interior Carpet	Burn/Holed/Cut	436	326	297	966	598	235
		Missing	436	326	297	966	598	235
	Interior Lighting	Broken/Damaged	54	32	114	100	34	28
		Missing	54	32	114	100	34	28
	Key	Broken/Damaged	265	265	265	265	265	265
		Missing	265	265	265	265	265	265
	Luggage Cover	Broken/Damaged	120					
		Missing	120					
	Rear View Mirror	Broken/Damaged	100	455	68	99	28	549
		Missing	100	455	68	99	28	549
	Rear Armrest	Broken/Damaged	179	179	179	179	179	179
Missing		179	179	179	179	179	179	
Rear Left Seat Back Cover	Broken/Damaged	133				162		
	Burn/Holed/Cut	133				162		
	Missing	133				162		
Rear Left Seat Base Cover	Broken/Damaged	207	485			242		
	Burn/Holed/Cut	207	485			242		
	Missing	207	485			242		
Rear Right Seat Back Cover	Broken/Damaged	74	256			108		
	Burn/Holed/Cut	74	256			108		
	Missing	74	256			108		
Rear Right Seat Base Cover	Broken/Damaged	134	390		285	169		
	Burn/Holed/Cut	134	390		285	169		
	Missing	134	390		285	169		

Light Damage Charges Schedule - Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van - 5 Seats	SWB Crew Van - 6 Seats
Interior	Roof lining	Broken/Damaged	292	170	1202	284	586	181
		Burn/Holed/Cut	292	170	1202	284	586	181
	Spare Wheel	Broken/Damaged	77	90	108	109	100	96
		Missing	77	90	108	109	100	96
	Speaker	Broken/Damaged	43	43	43	43	43	43
		Missing	43	43	43	43	43	43
	Sunvisor	Broken/Damaged	68	68	68	68	68	68
		Burn/Holed/Cut	68	68	68	68	68	68
		Missing	68	68	68	68	68	68
	Switches & Controls	Broken/Damaged	148	148	148	148	148	148
		Missing	148	148	148	148	148	148
	Window Handle	Broken/Damaged				18		
		Missing				18		
	Locking Wheel Bolt Key	Broken/Damaged	58	58	58	58	58	58
		Missing	58	58	58	58	58	58
	Full Valet Required	Broken/Damaged	60	60	60	60	60	60
		Soiled	60	60	60	60	60	60
	Interior Cleaning	Broken/Damaged	35	35	35	35	35	35
	Ply Lining	Broken/Damaged	155	155	155	155	155	155
		Missing	155	155	155	155	155	155
Accessories	Tool Kit	Missing	13	29	7	10		
	Hub Covers	Missing	22	29	42	40	17	30
		Scratch/Scuff <75mm Paint Damage	30	30	30	30	30	30
	Child Seat	Broken/Damaged	40	40	40	40	40	40
		Soiled	40	40	40	40	40	40