



**Light Damage Charges Schedule
February 2021**

Light Damage Charges Schedule - Cars

Area	Element	Type and Condition	Category									
			Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Front	Badge	Broken/Damaged/Missing	67	75	89	105	54	75	34	51	69	62
	Bonnet	Scratch/Scuff <75mm Paint Damage	256	295	317	339	343	404	430	412	298	291
		Scratch/Scuff - Medium 75-150mm	360	417	445	478	478	530	566	549	420	409
		Scratch/Scuff - Large 150mm+	410	483	515	560	553	547	574	576	488	474
		Dent - Small 25-75mm	294	334	355	378	381	443	468	450	337	330
		Dent - Medium 75-150mm	437	494	522	555	555	607	643	626	497	486
		Dent - Large 150mm+	526	599	630	675	669	663	689	691	603	590
		Bumper Trim	Broken/Damaged/Missing	52	48	50	67	63	60	116	73	59
	Bumper skirt	Broken/Damaged/Missing/Scuffed	36	81	99	76	98	66	41	97	146	154
	Front Bumper	Scratch/Scuff <75mm Paint Damage	275	270	297	281	272	253	246	261	312	298
		Scratch/Scuff - Medium 75-150mm	360	358	393	375	363	356	348	364	417	394
		Scratch/Scuff - Large 150mm+	360	358	393	375	363	356	349	364	417	385
		Dent - Small 25-75mm	314	309	335	320	311	291	285	299	351	337
		Dent - Medium 75-150mm	437	435	470	452	440	433	425	441	494	471
		Dent - Large 150mm+	476	474	509	491	479	471	464	480	532	500
	Fog Light (Right/Left)	Broken/Damaged/Missing	54	89	122	115	109	282	82	203	86	106
	Front Grille	Broken/Damaged/Missing	59	152	128	129	192	136	157	150	187	152
	Tow Eye Cover	Broken/Damaged/Missing	133	134	121	115	94	36	60	42	102	129
	Wiper Arm	Broken/Damaged/Missing	43	48	61	67	61	64	72	65	63	68
	Wiper Blade	Broken/Damaged/Missing	21	40	28	25	26	38	39	41	50	39
Number Plate	Broken/Damaged/Missing	25	25	25	25	25	25	25	25	25	25	
Windscreen	Glass chip 5-10mm	35	35	35	35	35	35	35	35	35	35	
Side (Right/Left)	Door (Front/Rear)	Scratch/Scuff <75mm Paint Damage	266	250	257	265	261	253	263	267	268	287
		Scratch/Scuff - Medium 75-150mm	517	480	493	510	512	451	467	486	535	575
		Scratch/Scuff - Large 150mm+	713	663	678	703	712	589	610	642	750	808
		Dent - Small 25-75mm	305	288	296	304	299	292	301	306	307	325
		Dent - Medium 75-150mm	594	557	570	587	589	528	544	563	612	652
		Dent - Large 150mm+	828	778	794	818	827	705	726	758	865	923
	Door Handle (Front/Rear)	Broken/Damaged	137	181	175	170	194	76	63	99	200	129
		Scratch/Scuff <75mm Paint Damage	133	134	130	134	129	91	88	93	133	123
	Door Aperture Seal	Broken/Damaged/Missing	50	65	73	68	100	96	72	104	94	135
	Front Wing	Scratch/Scuff <75mm Paint Damage	176	174	179	184	183	194	201	196	183	191
		Scratch/Scuff - Medium 75-150mm	384	374	380	393	400	363	379	382	411	433
		Scratch/Scuff - Large 150mm+	429	415	423	440	444	387	400	409	457	483
		Dent - Small 25-75mm	214	213	217	222	222	233	240	235	221	230
		Dent - Medium 75-150mm	461	451	457	470	477	440	456	459	488	510
		Dent - Large 150mm+	545	531	539	556	559	502	516	524	573	599
	Fuel Flap	Broken/Damaged	185	167	188	189	153	102	148	124	184	177
		Scratch/Scuff <75mm Paint Damage	133	131	132	136	122	59	99	79	135	120
	Side Indicator Repeater	Broken/Damaged/Missing	22	30	45	42	38	58	60	58	54	34
	Door Mirror Glass	Broken/Damaged/Missing	40	48	57	69	98	180	179	164	46	51
	Mirror Housing	Scratch/Scuff <75mm Paint Damage	65	65	65	65	65	65	65	65	65	65
		Broken/Damaged/Missing	108	178	195	239	282	323	402	360	360	224
	Moulding (Front/Rear)	Broken/Damaged/Missing	59	156	43	78	103	100	128	178	148	175
	Rear Wing	Scratch/Scuff <75mm Paint Damage	253	226	240	222	287	253	270	262	289	335
		Scratch/Scuff - Medium 75-150mm	492	443	470	452	558	446	472	472	540	639
		Scratch/Scuff - Large 150mm+	565	507	535	509	619	472	495	503	604	736
		Dent - Small 25-75mm	291	265	278	261	326	291	308	300	328	373
		Dent - Medium 75-150mm	569	520	547	529	635	523	549	549	617	716
Dent - Large 150mm+		681	623	650	625	735	588	611	618	720	852	

Light Damage Charges Schedule - Cars

Area	Element	Type and Condition	Category									
			Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Side (Right/Left)	Pillar A	Scratch/Scuff <75mm Paint Damage	156	171	193	172	215	163	172	171	184	152
		Scratch/Scuff - Medium 75-150mm	217	237	264	239	287	197	239	211	259	211
		Scratch/Scuff - Large 150mm+	236	259	288	260	318	200	274	218	290	225
		Dent - Small 25-75mm	195	210	231	211	254	202	210	209	223	190
		Dent - Medium 75-150mm	294	314	341	316	364	274	316	288	336	288
		Dent - Large 150mm+	352	374	404	376	433	316	389	333	406	341
	Pillar B	Scratch/Scuff <75mm Paint Damage	174	181	209	185	225	214	207	216	230	181
		Scratch/Scuff - Medium 75-150mm	242	252	294	259	314	260	247	265	325	252
		Scratch/Scuff - Large 150mm+	264	277	323	287	337	269	249	272	356	277
		Dent - Small 25-75mm	212	220	247	223	263	253	246	254	269	219
		Dent - Medium 75-150mm	319	329	371	336	391	337	324	342	402	329
		Dent - Large 150mm+	379	392	438	402	452	385	365	387	472	393
	Pillar D	Scratch/Scuff <75mm Paint Damage								181		164
		Scratch/Scuff - Medium 75-150mm								181		181
		Scratch/Scuff - Large 150mm+								181		186
		Dent - Small 25-75mm								219		202
		Dent - Medium 75-150mm								258		258
		Dent - Large 150mm+								296		302
	Sill	Scratch/Scuff <75mm Paint Damage	174	216	188	178	225	197	211	206	194	175
		Scratch/Scuff - Medium 75-150mm	243	305	261	247	313	278	256	266	264	243
		Scratch/Scuff - Large 150mm+	265	347	292	273	354	283	252	273	291	266
		Dent - Small 25-75mm	213	255	227	217	263	236	250	245	232	214
		Dent - Medium 75-150mm	320	382	338	324	390	355	333	343	341	320
		Dent - Large 150mm+	381	463	407	389	470	398	367	388	407	381
	Underside Protection	Broken/Damaged/Missing	68	113	106	106	75	73	66	68	128	90
	Wheel Trim (Front/Rear)	Broken/Damaged/Missing	37	31	43	43	46			37	52	58
	Wing Extension /Trim	Broken/Damaged/Missing/Scuffed	60	51	39	70	92		96	164	57	34
Door Glass (Front/Rear)	Glass chip 5-10mm	35	35	35	35	35	35	35	35	35	35	
Alloy/Steel Wheel (Front/Rear)	Scratch/Scuff <75mm Paint Damage	65	65	65	65	65	65	65	65	65	65	
Rear Sliding Door	Scratch/Scuff <75mm Paint Damage			431					692	431	440	
	Scratch/Scuff - Medium 75-150mm			757					1216	757	796	
	Scratch/Scuff - Large 150mm+			1026					1494	1026	1083	
	Dent - Small 25-75mm			470					730	470	478	
	Dent - Medium 75-150mm			834					1293	834	873	
	Dent - Large 150mm+			1142					1609	1142	1198	
Rear	Rear Badge	Broken/Damaged/Missing	52	40	43	51	41	34	28	35	42	37
	Tailgate/Boot Lid	Scratch/Scuff <75mm Paint Damage	251	265	269	279	273	281	297	282	301	325
		Scratch/Scuff - Medium 75-150mm	350	369	372	385	377	356	375	362	420	460
		Scratch/Scuff - Large 150mm+	399	421	419	428	430	365	379	380	480	539
		Dent - Small 25-75mm	289	303	308	318	312	319	336	321	340	364
		Dent - Medium 75-150mm	427	446	449	462	454	433	452	439	497	537
		Dent - Large 150mm+	515	537	534	544	545	480	495	495	595	654

Light Damage Charges Schedule - Cars

			Category									
Area	Element	Type and Condition	Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Rear	Rear Bumper	Scratch/Scuff <75mm Paint Damage	258	249	301	322	276	276	274	284	306	315
		Scratch/Scuff - Medium 75-150mm	344	333	404	433	369	387	386	395	411	418
		Scratch/Scuff - Large 150mm+	344	333	404	433	369	387	386	395	411	405
		Dent - Small 25-75mm	296	287	339	360	314	315	312	323	344	354
		Dent - Medium 75-150mm	421	410	481	510	446	464	463	472	488	495
		Dent - Large 150mm+	459	448	520	548	484	502	502	510	526	520
	Rear Fog Lamp (Right/Left)	Broken/Damaged/Missing	74	48	107	42	43			100	101	
	Rear Light (Right/Left)	Broken/Damaged/Missing	114	122	155	151	173	201	209	204	166	173
	Rear plate light	Broken/Damaged/Missing	21	18	28	30	30	19	20	18	21	31
	Rear Spoiler	Scratch/Scuff <75mm Paint Damage		207	179	168	100	105	54	115		
		Scratch/Scuff - Medium 75-150mm		283	246	236	143	146	84	165		
		Scratch/Scuff - Large 150mm+		283	246	252	143	144	84	165		
		Dent - Small 25-75mm		245	215	202	118	129	63	144		
		Dent - Medium 75-150mm		360	318	304	178	194	103	222		
		Dent - Large 150mm+		398	354	355	196	215	113	250		
	Rear Lower Bumper Valance	Scratch/Scuff <75mm Paint Damage	135	160	186	164	211	166	185	147	200	177
		Scratch/Scuff - Medium 75-150mm	197	227	285	232	290	233	257	191	271	243
		Scratch/Scuff - Large 150mm+	197	227	285	232	290	232	255	191	271	243
		Dent - Small 25-75mm	173	198	225	203	250	205	224	185	238	216
		Dent - Medium 75-150mm	274	304	362	309	367	310	334	268	348	320
		Dent - Large 150mm+	312	342	401	348	405	348	371	306	386	359
	Tow Eye Cover	Broken/Damaged/Missing	137	113	62	44	69	102	54	60	81	112
	Wiper Arm	Broken/Damaged/Missing	50	44	40	39	35	44	52	41	35	44
	Wiper Blade	Broken/Damaged/Missing	15	21	18	16	15	23	20	22	14	18
	Rear Screen	Glass chip 5-10mm	35	35	35	35	35	35	35	35	35	35
	Number Plate	Broken/Damaged/Missing	25	25	25	25	25	25	25	25	25	25
	Rear Loading Door	Scratch/Scuff <75mm Paint Damage			258						258	305
		Scratch/Scuff - Medium 75-150mm			363						363	428
		Scratch/Scuff - Large 150mm+			418						418	498
		Dent - Small 25-75mm			297						297	343
		Dent - Medium 75-150mm			440						440	505
		Dent - Large 150mm+			534						534	613
Roof	Aerial Mast	Broken/Damaged/Missing	12	20	38	32	36	192		18	11	18
	Roof	Scratch/Scuff <75mm Paint Damage	205	369	400	409	413	379	408	409	496	623
		Scratch/Scuff - Medium 75-150mm	285	517	564	575	580	501	538	546	705	890
		Scratch/Scuff - Large 150mm+	320	608	662	687	679	518	547	578	844	1077
		Dent - Small 25-75mm	243	407	439	448	451	418	447	448	535	661
		Dent - Medium 75-150mm	362	594	641	652	657	578	615	623	782	967
		Dent - Large 150mm+	436	723	778	802	794	633	662	694	960	1193
Interior	Boot Floor Covering	Broken/Damaged/Missing	118	148	193	143	226	79	117	134	257	456
	Centre Console	Broken/Damaged/Missing	56	127	162	204	301	424	567	508	177	103
		Burn/Holed/Cut	65	65	65	65	65	65	65	65	65	65
	Door Panel	Burn/Holed/Cut	65	65	65	65	65	65	65	65	65	65
		Missing	198	453	253	409	328	271	501	349	519	415
	Front Left Seat Back Cover	Burn/Holed/Cut	65	65	65	65	65	65	65	65	65	65
	Front Left Seat Base Cover	Burn/Holed/Cut	65	65	65	65	65	65	65	65	65	65
	Front Right Seat Back Cover	Burn/Holed/Cut	65	65	65	65	65	65	65	65	65	65
	Front Right Seat Base Cover	Burn/Holed/Cut	65	65	65	65	65	65	65	65	65	65
	Gear Lever Gaiter	Broken/Damaged/Missing	116	77	303	88	142	108	89	101	167	112
		Burn/Holed/Cut	116	77	303	88	142	108	89	101	167	112

Light Damage Charges Schedule - Cars

Area	Element	Type and Condition	Category									
			Mini	Economy	Compact	Intermediate	Standard	Premium	Luxury	Prestige	MPV Mini	MPV Medium
Interior	Glove Compartment	Broken/Damaged/Missing	158	163	157	140	227	301	204	307	98	111
	Head Restraint	Broken/Damaged/Missing	163	163	163	163	163	163	163	163	163	163
	Interior Carpet	Burn/Holed/Cut	65	65	65	65	65	65	65	65	65	65
	Interior Lighting	Broken/Damaged/Missing	37	47	106	65	233	132	248	221	56	54
	Key	Broken/Damaged/Missing	283	168	232	184	218	408	354	307	190	240
	Luggage Cover	Broken/Damaged/Missing	70	127	182	161	250	334	552	323	322	320
	Rear View Mirror	Broken/Damaged/Missing	93	128	132	228	152	358	352	343	172	171
	Rear Left Seat Back Cover	Burn/Holed/Cut	65	65	65	65	65	65	65	65	65	65
	Rear Left Seat Base Cover	Burn/Holed/Cut	65	65	65	65	65	65	65	65	65	65
	Rear Right Seat Back Cover	Burn/Holed/Cut	65	65	65	65	65	65	65	65	65	65
	Rear Right Seat Base Cover	Burn/Holed/Cut	65	65	65	65	65	65	65	65	65	65
	Roof lining	Burn/Holed/Cut	100	100	100	100	100	100	100	100	100	100
	SD Card	Broken/Damaged/Missing	55	55	55	65	65	400	202	202	250	250
	Speaker	Broken/Damaged/Missing	37	43	43	91	76	44	208	208	91	76
	Sunvisor	Broken/Damaged/Missing	37	109	68	101	95	54	105	105	101	95
		Burn/Holed/Cut	37	109	68	101	95	54	105	105	101	95
	Window Handle	Broken/Damaged/Missing	12	12	19							22
	Locking Wheel Bolt Key	Broken/Damaged/Missing	165	165	165	165	165	165	165	165	165	165
Accessories	Tool Kit	Missing	30	52	31	63	56	20	22	23	27	44
	Hub Covers	Missing	28	21	37	22	30	26	28	27	29	23
		Scratch/Scuff <75mm Paint Damage	30	30	30	30	30	30	30	30	30	30
	Decals	Broken/Damaged	30	30	30	30	30	30	30	30	30	30
		Missing	97	97	97	97	97	97	97	97	97	97

Light Damage Charges Schedule - Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van - 5 Seats	SWB Crew Van - 6 Seats
Front	Badge	Broken/Damaged/Missing	70	104	40	58	64	43
	Bonnet	Scratch/Scuff <75mm Paint Damage	282	257	295	361	273	261
		Scratch/Scuff - Medium 75-150mm	397	361	400	509	385	369
		Scratch/Scuff - Large 150mm+	459	416	446	600	443	425
		Dent - Small 25-75mm	320	296	333	400	312	300
		Dent - Medium 75-150mm	474	438	477	586	462	446
		Dent - Large 150mm+	574	531	562	716	559	540
	Bumper Trim	Broken/Damaged/Missing	54	36	37	69	42	56
	Bumper Skirt	Broken/Damaged/Missing/Scuffed	74	134	58	99	93	114
	Front Bumper	Scratch/Scuff <75mm Paint Damage	436	353	272	290	314	246
		Scratch/Scuff - Medium 75-150mm	583	473	355	380	420	327
		Scratch/Scuff - Large 150mm+	583	502	355	380	462	320
		Dent - Small 25-75mm	474	391	310	329	353	285
		Dent - Medium 75-150mm	660	550	432	457	497	404
		Dent - Large 150mm+	698	618	470	495	578	435
	Fog Light (Right/Left)	Broken/Damaged/Missing	104	94		215	85	
	Front Grille	Broken/Damaged/Missing	184	126	228	280	138	108
	Tow Eye Cover	Broken/Damaged/Missing	31	28	20		44	63
	Wiper Arm	Broken/Damaged/Missing	47	57	57	63	58	74
	Wiper Blade	Broken/Damaged/Missing	41	42	19	21	43	40
	Number Plate	Broken/Damaged/Missing	25	25	25	25	25	25
	Windscreen	Glass chip 5-10mm	35	35	35	35	35	35
	Side (Right/Left)	Door (Front/Rear)	Scratch/Scuff <75mm Paint Damage	288	315	307	257	294
Scratch/Scuff - Medium 75-150mm			567	673	674	544	606	658
Scratch/Scuff - Large 150mm+			789	974	982	784	863	954
Dent - Small 25-75mm			327	354	345	295	333	348
Dent - Medium 75-150mm			644	750	751	621	683	735
Dent - Large 150mm+			904	1089	1098	900	979	1069
Door Handle (Front/Rear)		Broken/Damaged	55	138	44	74	36	29
		Scratch/Scuff <75mm Paint Damage	133	132	117	133	119	
Door Aperture Seal		Broken/Damaged/Missing	72	66	86	61	55	53
Front Wing		Scratch/Scuff <75mm Paint Damage	180	190	216	195	185	183
		Scratch/Scuff - Medium 75-150mm	409	491	542	456	448	478
		Scratch/Scuff - Large 150mm+	456	539	587	506	495	525
		Dent - Small 25-75mm	219	228	255	234	223	221
		Dent - Medium 75-150mm	486	568	619	533	525	555
		Dent - Large 150mm+	571	654	702	622	611	640
Fuel Flap		Broken/Damaged	175	179	183	213	175	159
		Scratch/Scuff <75mm Paint Damage	134	135	129	139	134	114
Side Indicator Repeater		Broken/Damaged/Missing	14	22	43	41	24	30
Door Mirror Glass		Broken/Damaged/Missing	34	55	49	56	35	34
Mirror Housing		Scratch/Scuff <75mm Paint Damage	65	65	65	65	65	65
		Broken/Damaged/Missing	286	180	193	231	188	184
Moulding (Front/Rear)		Broken/Damaged/Missing	129	84	64		95	43

Light Damage Charges Schedule - Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van - 5 Seats	SWB Crew Van - 6 Seats
Side (Right/Left)	Rear Wing	Scratch/Scuff <75mm Paint Damage	248	390	530	384	322	352
		Scratch/Scuff - Medium 75-150mm	505	781	994	728	647	724
		Scratch/Scuff - Large 150mm+	575	899	1120	846	742	828
		Dent - Small 25-75mm	287	429	568	422	361	391
		Dent - Medium 75-150mm	582	858	1071	805	724	801
		Dent - Large 150mm+	691	1014	1235	961	858	943
	Pillar A	Scratch/Scuff <75mm Paint Damage	183	162	155	162	198	162
		Scratch/Scuff - Medium 75-150mm	253	223	202	226	270	223
		Scratch/Scuff - Large 150mm+	280	240	215	247	297	240
		Dent - Small 25-75mm	221	201	194	200	237	201
		Dent - Medium 75-150mm	330	300	279	303	347	300
		Dent - Large 150mm+	396	355	330	362	412	355
	Pillar B	Scratch/Scuff <75mm Paint Damage	198	219	201	208	214	219
		Scratch/Scuff - Medium 75-150mm	272	302	267	297	289	303
		Scratch/Scuff - Large 150mm+	304	343	295	332	321	343
		Dent - Small 25-75mm	237	258	239	247	252	258
		Dent - Medium 75-150mm	349	379	344	374	366	380
		Dent - Large 150mm+	420	458	410	448	436	459
	Pillar C	Scratch/Scuff <75mm Paint Damage	153	147	170	194	161	147
		Scratch/Scuff - Medium 75-150mm	155	147	177	267	161	147
		Scratch/Scuff - Large 150mm+	156	147	179	298	161	147
Dent - Small 25-75mm		192	186	209	232	199	186	
Dent - Medium 75-150mm		232	224	254	344	238	224	
Dent - Large 150mm+		271	263	295	414	276	263	
Pillar D	Scratch/Scuff <75mm Paint Damage	151	163	167		165	168	
	Scratch/Scuff - Medium 75-150mm	156	211	219		220	210	
	Scratch/Scuff - Large 150mm+	158	228	241		239	224	
	Dent - Small 25-75mm	189	201	205		203	206	
	Dent - Medium 75-150mm	233	288	296		297	287	
	Dent - Large 150mm+	274	343	357		354	340	
Sill	Scratch/Scuff <75mm Paint Damage	181	258	166	170	209	202	
	Scratch/Scuff - Medium 75-150mm	251	356	222	238	289	276	
	Scratch/Scuff - Large 150mm+	278	405	238	262	325	307	
	Dent - Small 25-75mm	219	296	204	209	248	241	
	Dent - Medium 75-150mm	328	433	299	315	366	353	
	Dent - Large 150mm+	394	521	353	377	440	422	
Underside Protection	Broken/Damaged/Missing	88	78	57	140	71	71	
Wheel Trim (Front/Rear)	Broken/Damaged/Missing	41	46	30		35	45	
Wing Extension /Trim	Broken/Damaged/Missing/Scuffed	47	34	27		38	33	
Door Glass (Front/Rear)	Glass chip 5-10mm	35	35	35	35	35	35	
Alloy/Steel Wheel (Front/Rear)	Scratch/Scuff <75mm Paint Damage	65	65	65	65	65	65	

Light Damage Charges Schedule - Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van - 5 Seats	SWB Crew Van - 6 Seats
Side (Right/Left)	Left Side Rear Panel	Scratch/Scuff <75mm Paint Damage	248	390	530	384	322	352
		Scratch/Scuff - Medium 75-150mm	505	781	994	728	647	724
		Scratch/Scuff - Large 150mm+	556	880	1100	827	723	808
		Dent - Small 25-75mm	287	429	568	422	361	391
		Dent - Medium 75-150mm	582	858	1071	805	724	801
		Dent - Large 150mm+	672	995	1216	942	838	924
	Right Side Rear Panel	Scratch/Scuff <75mm Paint Damage	319	516	530	384	423	559
		Scratch/Scuff - Medium 75-150mm	606	961	994	728	791	1020
		Scratch/Scuff - Large 150mm+	683	1106	1100	827	904	1180
		Dent - Small 25-75mm	357	555	568	422	461	598
		Dent - Medium 75-150mm	683	1038	1071	805	868	1097
		Dent - Large 150mm+	799	1221	1216	942	1019	1295
	Side Wall	Scratch/Scuff <75mm Paint Damage	513		510			
		Scratch/Scuff - Medium 75-150mm	1007		966			
		Scratch/Scuff - Large 150mm+	1432		1334			
		Dent - Small 25-75mm	552		548			
		Dent - Medium 75-150mm	1084		1043			
		Dent - Large 150mm+	1547		1449			
Rear Sliding Door	Scratch/Scuff <75mm Paint Damage	441	569	561		460	402	
	Scratch/Scuff - Medium 75-150mm	788	1043	1038		848	793	
	Scratch/Scuff - Large 150mm+	1068	1438	1411		1170	1123	
	Dent - Small 25-75mm	479	608	600		499	441	
	Dent - Medium 75-150mm	865	1120	1115		925	870	
	Dent - Large 150mm+	1184	1553	1526		1285	1238	
Rear	Rear Badge	Broken/Damaged/Missing	42	31	37	40	35	33
	Tailgate/Boot Lid	Scratch/Scuff <75mm Paint Damage	314	395			395	
		Scratch/Scuff - Medium 75-150mm	445	558			558	
		Scratch/Scuff - Large 150mm+	516	662			662	
		Dent - Small 25-75mm	352	434			434	
		Dent - Medium 75-150mm	522	635			635	
		Dent - Large 150mm+	632	778			778	
	Rear Bumper	Scratch/Scuff <75mm Paint Damage	324	307	231	208	341	
		Scratch/Scuff - Medium 75-150mm	459	434	245	292	478	
		Scratch/Scuff - Large 150mm+	459	400	245	333	478	
		Dent - Small 25-75mm	362	345	270	247	379	
		Dent - Medium 75-150mm	536	511	322	369	555	
		Dent - Large 150mm+	574	516	360	448	594	
	Rear Fog Lamp (Right/Left)	Broken/Damaged/Missing	53			98		
	Rear Light (Right/Left)	Broken/Damaged/Missing	127	135	117	140	132	130
	Rear plate light	Broken/Damaged/Missing	20	21	19	32	21	26
	Tow Eye Cover	Broken/Damaged/Missing	76	57	100		52	47
	Wiper Arm	Broken/Damaged/Missing	36				38	64
Wiper Blade	Broken/Damaged/Missing	17				18	22	
Rear Screen	Glass chip 5-10mm	35	35	35	35	35	35	
Number Plate	Broken/Damaged/Missing	25	25	25	25	25	25	

Light Damage Charges Schedule - Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van - 5 Seats	SWB Crew Van - 6 Seats
Rear	Rear Loading Door	Scratch/Scuff <75mm Paint Damage	309	296	374	246	299	287
		Scratch/Scuff - Medium 75-150mm	434	415	521	346	419	402
		Scratch/Scuff - Large 150mm+	508	482	591	397	487	466
		Dent - Small 25-75mm	348	335	412	284	337	326
		Dent - Medium 75-150mm	511	492	598	423	496	479
		Dent - Large 150mm+	624	598	706	512	602	581
	Step	Broken/Damaged/Missing		350	350	350	350	350
	Tail-lift	Broken/Damaged/Missing		450	450	450	450	450
Roof	Aerial Mast	Broken/Damaged/Missing	18	15	51	47	24	23
	Roof	Scratch/Scuff <75mm Paint Damage	602	498	458	356	612	755
		Scratch/Scuff - Medium 75-150mm	859	709	637	504	874	1083
		Scratch/Scuff - Large 150mm+	1036	850	720	592	1055	1320
		Dent - Small 25-75mm	640	536	497	395	650	793
		Dent - Medium 75-150mm	936	786	714	581	951	1160
		Dent - Large 150mm+	1151	966	836	708	1171	1436
Interior	Bulkhead	Broken/Damaged/Missing	414	414	414	414	414	414
	Centre Console	Broken/Damaged/Missing	95	98	90	140	73	85
		Burn/Holed/Cut	65	65	65	65	65	65
	Door Panel	Burn/Holed/Cut	65	65	65	65	65	65
		Missing	209	350	171	340	225	380
	Front Left Seat Back Cover	Burn/Holed/Cut	65	65	65	65	65	65
	Front Left Seat Base Cover	Burn/Holed/Cut	65	65	65	65	65	65
	Front Right Seat Back Cover	Burn/Holed/Cut	65	65	65	65	65	65
	Front Right Seat Base Cover	Burn/Holed/Cut	65	65	65	65	65	65
	Gear Lever Gaiter	Broken/Damaged/Missing	134	54	117	40	94	48
		Burn/Holed/Cut	134	54	117	40	94	48
	Glove Compartment Lid	Broken/Damaged/Missing	103	129	120	194	125	101
	Head Restraint	Broken/Damaged/Missing	156	156	156	156	156	156
	Interior Carpet	Burn/Holed/Cut	65	65	65	65	65	65
	Interior Lighting	Broken/Damaged/Missing	30	68	141	63	54	71
	Key	Broken/Damaged/Missing	220	397	259	127	236	236
	Luggage Cover	Broken/Damaged/Missing	306					
	Rear View Mirror	Broken/Damaged/Missing	50	315	128	89	51	49

Light Damage Charges Schedule – Vans

Area	Element	Type and Condition	Category					
			CDV	SWB	LWB	Double Cab Pickups	CDV Crew Van - 5 Seats	SWB Crew Van - 6 Seats
Interior	Rear Left Seat Back Cover	Burn/Holed/Cut	65	65	65	65	65	65
	Rear Left Seat Base Cover	Burn/Holed/Cut	65	65	65	65	65	65
	Rear Right Seat Back Cover	Burn/Holed/Cut	65	65	65	65	65	65
	Rear Right Seat Base Cover	Burn/Holed/Cut	65	65	65	65	65	65
	Roof lining	Burn/Holed/Cut	100	100	100	100	100	100
	Speaker	Broken/Damaged/Missing	44	44	44	44	44	44
	Sunvisor	Broken/Damaged/Missing	70	70	70	70	70	70
		Burn/Holed/Cut	70	70	70	70	70	70
	Window Handle	Broken/Damaged/Missing	19	22	24	41	22	
	Locking Wheel Bolt Key	Broken/Damaged/Missing	165	165	165	165	165	165
Ply Lining	Broken/Damaged/Missing	160	160	160	160	160	160	
Accessories	Tool Kit	Missing	19		58	70	14	
	Hub Covers	Missing	28	17	29	22	18	17
		Scratch/Scuff <75mm Paint Damage	30	30	30	30	30	30
	Decals	Broken/Damaged	63	63	63	63	63	63
		Missing	221	221	221	221	221	221